










```
sketch_jan20b.ino
52
53 if (flameValue == 0 && temperature > 30) {
54   // Strong fire confirmation
55   digitalWrite(LED_PIN, HIGH);
56   Serial.println("🔥 FIRE CONFIRMED (Flame + Heat)");
57 }
58 else if (flameValue == 0) {
59   // Flame detected only
60   digitalWrite(LED_PIN, HIGH);
61   Serial.println("⚠️ FIRE RISK (Flame Detected)");
62 }
63 else if (temperature > 45) {
64   // Temperature-based warning
65   digitalWrite(LED_PIN, HIGH);
66   Serial.println("⚠️ FIRE RISK (High Temperature)");
67 }
68 else {
69   // Safe condition
70   digitalWrite(LED_PIN, LOW);
71   Serial.println("Environment Safe");
72 }
73
74 Serial.println("-----");
75 delay(2000);
76 }
77
```

Output Serial Monitor X

Message (Enter to send message to 'Arduino Uno' on 'COM11')

New Line 9600 baud

⚠️ FIRE RISK (Flame Detected)

Temperature: 20.30 °C | Humidity: 71.10 % | Flame Value: 0

⚠️ FIRE RISK (Flame Detected)
