

- Q.25 Explain relation between screen pack and breaker plate.
- Q.26 Explain extruder performance their curves.
- Q.27 Explain importance of “Nip rolls”.
- Q.28 Explain different types of screw and their importance.
- Q.29 Give four defects and remedies of Blow moulding process.
- Q.30 Give five defects of extrusion process.
- Q.31 Give advantages of Stretch blow molding.
- Q.32 Explain basic principle of blow moulding.
- Q.33 Discuss Wood- plastic laminates.
- Q.34 Explain Take-off devices used in extrusion.
- Q.35 Discuss bubble casing.

#### **SECTION-D**

**Note:** Long answer type questions. Attempt any two questions out of three questions. (2x10=20)

- Q.36 Explain principle, construction and working blow moulding machine neat sketch.
- Q.37 Explain :
- Twin screw extruder
  - Advantages and disadvantages of multilayer packaging.
- Q.38 Discuss flow line diagram of wire and cable coating with neat sketch.

No. of Printed Pages : 4  
Roll No. ....

122252/32252

#### **Plastic Engineering** **Subject:- Plastic Processing Techniques - II**

Time : 3Hrs.

M.M. : 100

#### **SECTION-A**

**Note:** Multiple choice questions. All questions are compulsory (10x1=10)

- Q.1 A Parison can be \_\_\_\_\_.
- Extruded
  - injection molded
  - Extruded & injection molded
  - Compression molded
- Q.2 The polymer material is fed into the extruder through the \_\_\_\_\_.
- Barrel
  - Hopper
  - Screw
  - Die
- Q.3 A blow mould consists of \_\_\_\_\_.
- One male half
  - Two female halves
  - One male and one female half
  - Two male halves
- Q.4 The gauge pressure of air used to inflate parison is

between \_\_\_\_\_.

- a) 40-150 psi
- b) 250-300 psi
- c) 40-150 psi
- d) 250-300 psi

Q.5 The part weight is directly proportional to the \_\_\_\_\_ of the component.

- a) Shrinkage
- b) Warpage
- c) Wall thickness
- d) Bend

Q.6 The plastic is first melted and extruded as hollow tube called \_\_\_\_\_.

- a) Mandrel
- b) Parison
- c) Pipe
- d) Screw

Q.7 If the screw temperature does not reach the set value, the \_\_\_\_\_ must be replaced.

- a) Micrometer
- b) Thermocouple
- c) Ammeter
- d) Thermometer

Q.8 \_\_\_\_\_ enhances mixing of the material.

- a) Twin screw extruder
- b) Single screw extruder
- c) Hand extruder
- d) Barrel

Q.9 In compression zone \_\_\_\_\_ takes place.

- a) Pumping
- b) Feeding
- c) Drying
- d) Plasticizing

Q.10 \_\_\_\_\_ helps bring the feedstock into the extruder

- a) Extruder screw
- b) Motor
- c) Die
- d) Barrel

## SECTION-B

**Note:** Objective type questions. All questions are compulsory. (10x1=10)

Q.11 Name two examples of paper-plastic laminates.

Q.12 What happens when the set temperature is low?

Q.13 Distance between consecutive flights is called a \_\_\_\_\_.

Q.14 Name two dies used in extrusion process.

Q.15 The portion of screw, which prevents the escape of the material, is known as \_\_\_\_\_.

Q.16 Name various materials used in multi layer packaging.

Q.17 In Extrusion process, cross section of the product at any point is \_\_\_\_\_.

Q.18 Define breaker plate.

Q.19 Expand ISBM.

Q.20 Define Screen packs.

## SECTION-C

**Note:** Short answer type questions. Attempt any twelve questions out of fifteen questions. (12x5=60)

Q.21 Define perform in blow moulding process.

Q.22 Discuss parison programming and its importance.

Q.23 Discuss applications and importance of metal - plastic laminates.

Q.24 Explain draw down ratio.