

- Q.31 Explain Prismatic Compass with diagram.
 - Q.32 Give the classification of survey based upon nature of field.
 - Q.33 What is Planimeter?
 - Q.34 What are the objects of surveying?
 - Q.35 Show contour to represent the following with sketches:-

- a) Valley
- b) Hill
- c) Vertical Cliff

SECTION-D

Note: Long answer type questions. Attempt any two questions out of three questions. (2x10=20)

- Q.36 What is Local Attraction? How it is detected? Give its causes.

Q.37 The following are the observed FB of the line in WCB, find out BB of the line:

 - FB of line AB = $142^{\circ}15'$
 - FB of line BC = $38^{\circ}00'$
 - FB of line CD = $313^{\circ}45'$
 - FB of line DE = $242^{\circ}30'$

Q.38 Write short notes on:

 - Plain Alidade
 - Metric chain

No. of Printed Pages : 4 180236/120236/030236
Roll No.

3rd Sem / Arch
Subject:- Surveying / Surveying- I

Time : 3Hrs. M.M. : 100

SECTION-A

Note: Multiple choice questions. All questions are compulsory (10x1=10)

- Q.1 Ranging rods have length either _____ or _____
a) 2m, 3m b) 5m, 6m
c) 1m, 4m d) 2m, 6m

Q.2 In a metric chain each meter length is divided into _____ Links.
a) 8 b) 9
c) 5 d) 4

Q.3 The box of the compass is made up of _____
a) Brass b) Iron
c) Steel d) Copper

Q.4 The size of the plane table is _____
a) 600 mm x 700 mm b) 750 mm x 900 mm
c) 450 mm x 600 mm d) 300 mm x 450 mm

Q.5 The accuracy of EDM devices are _____
a) 1 in 10000 b) 1 in 100000
c) 1 in 10 d) 1 in 100

Q.6 Which shaped lines indicate the presence of a ridge?
a) V-shaped b) L-shaped
c) U-shaped d) S-shaped

- Q.7 Fore bearing and back bearing differs by degrees.
 a) 180 b) 90
 c) 75 d) 50
- Q.8 Contours can be found in a _____ map.
 a) Political b) Topographical
 c) Physical d) Thematic
- Q.9 How many types of a compass are used in surveying?
 a) 3 b) 2
 c) 4 d) 1
- Q.10 Length of a link of Gunter's chain is _____
 a) 0.66 ft b) 0.45 ft
 c) 0.50 ft d) 0.70 ft

SECTION-B

- Note:** Objective type questions. All questions are compulsory. (10x1=10)
- Q.11 A metallic tape is made of _____ (cloth/steel)
- Q.12 TST is _____.(Total station Theodolite/tatal space thodolite)
- Q.13 For a well-conditioned triangle, no angle should be less than _____.(30°/60°)
- Q.14 FB and BB should differ by _____.(180°/90°)
- Q.15 A short offset does not have length greater than _____ meters.(15/20)
- Q.16 The box of the compass is made of _____. (brass /alloy)
- Q.17 The fiducial edge of alidade should be _____. (Straight/curve)

(2) 180236/120236/030236

- Q.18 20m chain is divided into _____ equal parts. (100/50)
 Q.19 The least count of telescopic levelling staff is _____. (5mm/10mm)

- Q.20 Fore sight is _____ reading of the setting of level.
 (first/last)

SECTION-C

Note: Short answer type questions. Attempt any twelve questions out of fifteen questions. (12x5=60)

- Q.21 Compare Prismatic compass and surveyor compass.
- Q.22 List the advantages and disadvantages of chain surveying.
- Q.23 Explain the Radiation method in Plane Table Surveying.
- Q.24 List advantages of Plane Table Surveying.
- Q.25 Define:
 a) Fore Sight b) Back sight
 c) Intermediate Sight d) Bench mark
 e) Change point
- Q.26 The length of the line measured with 20m chain was found to be 402m. The true length of line was 400m. Find the length of chain used.
- Q.27 Write the characteristics of Contours.
- Q.28 Define:
 a) arrow b) pegs
 c) plumb bob d) ranging rod
 e) contour map
- Q.29 Differentiate between plane and geodetic surveying
- Q.30 Explain GIS.

(3) 180236/120236/030236