

- Q.30 Explain the traversing method of plane table surveying.
- Q.31 Explain any three sources of error in plane table surveying.
- Q.32 What is surveying? What is the purpose of surveying?
- Q.33 Write any five advantages and disadvantages each of a plane table surveying.
- Q.34 Explain which types of measurements are taken on plane surveying.
- Q.35 Write any five advantages and disadvantages each of compass survey.

SECTION-D

Note: Long answer type questions. Attempt any two questions out of three questions. (10x2=20)

- Q.36 The following consecutive readings were taken with a level. The level was shifted after 4th, 7th and 10th readings. The first reading was taken on a B.M of R.L 150.000m. Draw out a page of level book, enter the readings and calculate the reduced levels of all the points by Height of instrument method. Apply the arithmetic check.

1.520, 0.965, 1.475, 1.545, 0.435, 2.545, 1.715, 1.630, 1.915, 0.860, 1.790, 1.365, 1.135

- Q.37 Enumerate and explain briefly instruments used in plane table surveying with sketches.
- Q.38 Describe the characteristics of contour?

No. of Printed Pages : 4 180236/120236/030236
Roll No.

3rd Sem / Arch
Subject:- Surveying/Surveying-I

Time : 3Hrs. M.M. : 100

SECTION-A

Note: Multiple choice questions. All questions are compulsory (10x1=10)

- Q.1 One hectare is equal to _____ Sqm.
 a) 10^6 b) 10^2
 c) 0^4 d) 10^8
- Q.2 The surface of still water is considered to be _____
 a) Parallax b) Level
 c) Temporary d) G.T.S
- Q.3 The Box of compass is made of _____
 a) Brass b) Aluminum
 c) iron d) Copper
- Q.4 The Prismatic compass can be used without fixing it on _____
 a) Plumb bob b) U-fork
 c) Alidade d) Tripod stand
- Q.5 FB and BB should differ by _____
 a) 180^0 b) 0^0
 c) 360^0 d) 270^0

(220) (4) 180236/120236/030236 (1) 180236/120236/030236

Q.6 The effect of curvature is to _____ the staff reading.

- a) Decrease
- b) Temporary
- c) Increase
- d) Last

Q.7 The curvature of earth is ignored in _____

- a) Contour
- b) Magnified
- c) MKS
- d) Plane surveying

Q.8 Reduced bearing is always less than _____

- a) 270°
- b) 370°
- c) 90°
- d) 0°

Q.9 Fore Sight is _____ reading of the setting of level.

- a) Last
- b) B.M
- c) Temporary
- d) First

Q.10 π radian is equal to _____ degree.

- a) 0°
- b) 90°
- c) 180°
- d) 270°

SECTION-B

Note: Objective type questions. All questions are compulsory. $(10 \times 1 = 10)$

Q.11 The metric system of measurement is known as _____

Q.12 The art of determining the _____ position of objects on the surface of earth is known as surveying.

Q.13 When the needle is deflected towards west of the true meridian it is said _____

Q.14 The datum adopted for India is mean sea level at _____

Q.15 The plane table survey is suitable for _____ scale mapping.

Q.16 Name any two instruments used for taking measurement?

Q.17 A 20 meter chain have _____ links.

Q.18 Define whole circle bearing.

Q.19 Length of an Engineer chain is _____ ft.

Q.20 Define Back bearing.

SECTION-C

Note: Short answer type questions. Attempt any twelve questions out of fifteen questions. $(12 \times 5 = 60)$

Q.21 What are the function of a prismatic compass?

Q.22 Enumerate the different sources sources of error's in plane table surveying.

Q.23 What is the local attraction? How it is detected and removed?

Q.24 Write short note on height of collimation method.

Q.25 Write short note on:

- A) whole circle bearing

Q.26 Define magnetic declination. What are different types of variation in declination?

Q.27 Explain in brief temporary adjustment of dumpy level.

Q.28 Explain the principles of surveying with sketches.

Q.29 Define plane surveying and geodetic surveying.