

- Q.25 Explain the working of cupola furnace.
- Q.26 Describe the uses of dial comparator. Explain its limitations.
- Q.27 Discuss various work holding devices of lathe.
- Q.28 Write a short note on micrometer. Also draw neat sketch.
- Q.29 Describe metals praying method and its types.
- Q.30 What is electroplating? Describe this process with diagram.
- Q.31 Discuss any five properties of a moulding sand.
- Q.32 Define tolerance and its types.
- Q.33 Write a short note on different pattern materials.
- Q.34 Give difference between “Go” and “Not -Go” gauge.
- Q.35 Explain the process of metal bending in detail.

SECTION-D

- Note:** Long answer type questions. Attempt any two questions out of three questions. (2x10=20)
- Q.36 Describe various casting defects and their remedies.
- Q.37 Briefly discuss about various lathe operations with neat sketches.
- Q.38 Explain the construction and working of shaper machine with neat sketch.

(20) (4) 180134/120134/030134

No. of Printed Pages : 4 180134/120134/030134
Roll No.

3rd Sem / Agri., Auto Subject:- Manufacturing Technology - I

Time : 3Hrs.

M.M. : 100

SECTION-A

Note: Multiple choice questions. All questions are compulsory (10x1=10)

- Q.1 It is an instrument used for angular measurement.
a) Dial gauge b) Vernier caliper
c) Sine bar d) Micrometer
- Q.2 Base of shaper machine is made up of _____.
a) Cast iron b) Concrete
c) Wrought iron d) Stainless steel
- Q.3 An operation of producing an external conical surface on a work piece is known as
a) Plain turning b) Taper turning
c) Step turning d) Facing
- Q.4 In moulding, the middle flask is known as
a) Drag b) Cheek
c) Cope d) None of these

(1) 180134/120134/030134

- Q.5 Core sand is also known as _____
- a) Parting sand b) Oil sand
c) Green sand d) Dry sand
- Q.6 Defects caused by patterns and moulding box equipment
- a) Fins b) Crush
c) Mismatch d) All of these
- Q.7 It is the extreme permissible to make the machine component.
- a) Fits b) Size
c) Limits d) Tolerances
- Q.8 An operation of reducing the diameter of a work-piece over a narrow surface is known as
- a) Knurling b) Counter boring
c) Facing d) Grooving
- Q.9 Clapper box is used for
- a) To ensure cutting action
b) To hold the tool
c) To lift tool in return stroke
d) To lift tool in cutting stroke
- Q.10 In an oil paint, turpentine oil is used as a
- a) Solvent b) Pigment
c) Base d) Vehicle

(2) 180134/120134/030134

SECTION-B

Note: Objective type questions. All questions are compulsory. (10x1=10)

- Q.11 Define furnace.
- Q.12 Define limit.
- Q.13 What is knurling.
- Q.14 Write uses of primer.
- Q.15 Write a use of micrometer.
- Q.16 Give any function of riser.
- Q.17 Deposition of a layer of superior metal on a metallic work piece is called _____.
- Q.18 _____ is a work holding device for lathe machine.
- Q.19 _____ is used for melting the material for casting.
- Q.20 State the name of gauge for checking height of a component.

SECTION-C

Note: Short answer type questions. Attempt any twelve questions out of fifteen questions. (12x5=60)

- Q.21 What is interchangeability? Explain its use.
- Q.22 Explain the various metals used in a cutting tool.
- Q.23 How base material is prepared prior to paint?
- Q.24 Write the names of any five types of pipe fittings.

(3) 180134/120134/030134