

- Q.29 Enlist the causes of instrumental errors in compass surveying.
- Q.30 Explain principle of leveling.
- Q.31 Describe benchmark and various types of benchmarks.
- Q.32 Name the different types of levels.
- Q.33 Define bubble line and axis of the bubble tube.
- Q.34 Define Reduced level and bench Mark.
- Q.35 Describe change point. and Back sight.

SECTION-D

Note: Long answer type questions. Attempt any two questions out of three questions. (2x10=20)

- Q.36 Explain the method of chaining on a sloping ground in detail.
- Q.37 Describe briefly various method of leveling.
- Q.38 Explain orientation and how it is done in Plane table.

No. of Printed Pages : 4
Roll No.

180236/120236/030236

3rd Sem / Arch

Subject : Surveying/ Surveying -I

Time : 3 Hrs.

M.M. : 100

SECTION-A

Note: Multiple choice questions. All questions are compulsory (10x1=10)

- Q.1 Two types of measurements
- a) linear measurements
 - b) angular measurement
 - c) both a and b
 - d) none of the above
- Q.2 Surveying in slopes and height are done by
- a) clinometer
 - b) ranging rod
 - c) plane table
 - d) theodolite
- Q.3 The principle of chain surveying is
- a) triangulation
 - b) manipulation
 - c) measurements
 - d) undulations
- Q.4 Arrows are also known as
- a) marking pens
 - b) marking pins
 - c) marking heads
 - d) marking arrows

- Q.5 Test gauge is used for testing
 a) tape b) chain
 c) theodolite d) cross-staff
- Q.6 The box of compass is made by
 a) steel b) wood
 c) brass d) plastic
- Q.7 F B and B B should differ by
 a) 360° b) 90°
 c) 120° d) 180°
- Q.8 Quadrantal bearings are measured with
 a) surveyor compass b) prismatic compass
 c) both a and b d) None of the above
- Q.9 Inaccessible points may be located by
 a) centering b) intersection
 c) contouring d) chaining
- Q.10 The plane table survey is suitable for
 a) Big area b) Small area
 c) hilly area d) both a and b

SECTION-B

Note: Objective type questions. All questions are compulsory. (10x1=10)

- Q.11 The metric system of measurement is known as_____.

- Q.12 A 20 m chain have _____ links.
- Q.13 In reciprocal ranging end stations are_____.
- Q.14 Handles are connected to link by_____.
- Q.15 Zero is marked at_____ in case of prismatic compass.
- Q.16 Offset road is used for taking_____ offsets.
- Q.17 Cumulative error is_____.
- Q.18 Reducing bearing is always less than_____.
- Q.19 Invar tape is used for_____ work.
- Q.20 Test gauge is used for testing_____.

SECTION-C

Note: Short answer type questions. Attempt any twelve questions out of fifteen questions. (12x5=60)

- Q.21 Define plane and geodetic surveying.
- Q.22 Define surveying with their four purpose.
- Q.23 Briefly describe the process of chaining on flat roof.
- Q.24 Enlist any five errors in chain surveying.
- Q.25 Define obstacle. How do we overcome the obstacle in chain surveying?
- Q.26 Define whole circle bearing and reduced bearing.
- Q.27 Define true meridian and Magnetic meridian.
- Q.28 Explain magnetic declination.