

No. of Printed Pages : 4
Roll No.

188551

Level-5, 1st Sem/ DVOC
(Medical Imaging Technology)
Subject : Electronic Measurement &
Instrumentation-I

Time : 2 Hrs.

M.M. : 50

SECTION-A

Note: Multiple choice questions. All questions are compulsory (5x1=5)

- Q.1 PMMC stands for
- a) Print Master Moving Coil
 - b) Permanent Magnet Moving Coil
 - c) Prime measurement magnetic coil
 - d) None of the above
- Q.2 SI temperate scale is shown in
- a) Kelvin
 - b) Farenheit
 - c) Celcius
 - d) Radium
- Q.3 Accuracy means
- a) Showing half the exact value
 - b) Repeating the same value
 - c) Closeness to exact value
 - d) Average of observed values

- Q.4 The central tendency in statistical analysis is
a) Mean b) Median
c) Mode d) All of the above
- Q.5 Relative errors is mostly shown in _____ form.
a) Decimals b) Romans
c) Fractions d) Percentage

SECTION-B

Note: Objective type questions. All questions are compulsory. (5x1=5)

- Q.6 A number that describes a sample value is called_____.
- Q.7 Name any two Unit systems other than SI units.
- Q.8 Voltmeter are connected in _____.
- Q.9 The Unit of resistance is _____.
- Q.10 Dimensional formula for force is _____.

SECTION-C

Note: Very Short answer type questions. Attempt any six questions out of eight questions. (6x5=30)

- Q.11 Explain various types of dimensions with example.
- Q.12 Differentiate between precision and resolution.

- Q.13 Write short note on the working of galvanometer.
- Q.14 Explain different types of probes with diagrams.
- Q.15 Discuss transistor voltmeter circuits.
- Q.16 The measurement of a voltage is 13.65 volts instead of actual 13.5 volts. Find the absolute and relative error.
- Q.17 Explain significant figures in a digital multi meter with example.
- Q.18 Write short note on series ohm meter.

SECTION-D

Note: Long answer type questions. Attempt any one questions out of two questions. (1x10=10)

- Q.19 Explain the types of errors and their significance.
- Q.20 What basic measurements are performed by Digital multimeters? Give the procedure of connections for at least two types of measurements.