


Q.25 Fig. shows an isometric view of an object. Study the drawing carefully and draw its front view and top view in first angle projection method.



No. of Printed Pages : 4
Roll No.

222015

Ist Year / Advance Diploma in Tool & Die Making
Subject : Engineering Drawing

Time : 3 Hrs.

M.M. : 60

SECTION-A

Note: Multiple choice questions. All questions are compulsory (6x1=6)

- Q.1 The edge of the board on which T-Square is made to slide is called its _____.
a) Working edge b) Straight edge
c) Chisel edge d) None of above
- Q.2 In a conic, the line passing through the fixed point and perpendicular to the fixed line is called the _____.
a) Focus b) Axis
c) Directrix d) Eccentricity
- Q.3 In _____ projection method, object comes between observer and plane
a) First angle b) Third angle
c) Both 'a' & 'b' d) None
- Q.4 For drawing of small components _____ scale is used.
a) Enlarging b) Reduced
c) Normal d) None

- Q.5 When a point is above HP its front view is ____ xy.
 a) Below b) Above
 c) Behind d) Front
- Q.6 When the axis of an object is perpendicular to the VP, it is ____ to the H.P.
 a) Perpendicular b) Vertical
 c) Parallel d) Horizontal

SECTION-B

Note: Objective/ Completion type questions. All questions are compulsory. (6x1=6)

- Q.7 Write the short cut key to draw a line.
- Q.8 If a point lies 8mm behind V.P. and 10mm above H.P., then it lies in which quadrant?
- Q.9 What is the angle of Acme threads?
- Q.10 Why second and fourth quadrants are not used in practice?
- Q.11 Classify engineering drawing.
- Q.12 On which plane, the top view of an object is shown?

SECTION-C

Note: Short answer type questions. Attempt any eight questions out of ten questions. (8x4=32)

- Q.13 Draw the development of a right cylinder.
- Q.14 Draw a hexagon when length of a side is 50mm.

- Q.15 Define any four editing commands of AutoCAD.
- Q.16 Draw the isometric projection of a circle having diameter 25mm diameters.
- Q.17 Explain sectional view.
- Q.18 Draw the free hand sketch of eye Bolt.
- Q.19 Explain different types of location tolerances.
- Q.20 Describe different types of welded joints.
- Q.21 Draw the isometric projection of a cylinder of base 50mm diameter and height 70mm with the axis vertical and horizontal.
- Q.22 Explain any four surface texture symbols.

SECTION-D

Note: Long answer type questions. Attempt any two questions out of three questions. (2x8=16)

- Q.23 Draw an ellipse whose major axis is 100mm and minor axis is 60mm.
- Q.24 Draw the projection of a cone of base 40mm diameter, axis 60mm long when it is resting with its base on H.P.