

- Q.19 Explain number of impressions and loading chamber design.
- Q.20 Explain various types of die material used in extrusion dies.
- Q.21 Explain die head assembly for blow mould.
- Q.22 Explain neck design for injection blow mould.

SECTION-D

Note: Long answer type questions. Attempt any two questions out of three questions. (2x8=16)

- Q.23 Write short on:
- Types of transfer moulds.
 - Die geometry, design of sprue and runners, gate used in plastic processing
- Q.24 Explain:
- Parison thickness control
 - Semi positive mould
- Q.25 Discuss with neat sketch:
- Pipe and tube extrusion die
 - Die used for making wire and cable coatings.

No. of Printed Pages : 4
Roll No.

222246

4th Sem. / Plastic Technology

Subject : Design of Dies and Moulds-II

Time : 3 Hrs.

M.M. : 60

SECTION-A

Note: Multiple choice questions. All questions are compulsory (6x1=6)

- Q.1 Which moulding process is associated with breathing?
- Transfer moulding
 - Injection moulding
 - Compression moulding
 - Extrusion moulding
- Q.2 What is the requirement for compression moulding process?
- Heat
 - Pressure
 - Heat and pressure
 - Air, Heat and pressure

- Q.3 There is no pinch off mark in _____.
 a) Extrusion Blow moulding
 b) Injection Blow moulding
 c) Injection moulding d) None of these
- Q.4 _____ cannot be avoided in compression moulds.
 a) Sprue b) Runner
 c) Gate d) Flash
- Q.5 What is the name of line which lies between two mould halves?
 a) Parting Line b) Center Line
 c) Matching Line d) Vertical Line
- Q.6 What we called the section of the mould where the parison is squeezed and welded together?
 a) Neck b) Gate
 c) Pinch off d) Mandrel

SECTION-B

Note: Objective/ Completion type questions. All questions are compulsory. (6x1=6)

- Q.7 Name the two materials used for blow moulding process.

- Q.8 _____ is the connecting member between gate and sprue bush.
- Q.9 _____ is round cross section and has taper along its length.
- Q.10 _____ type of cooling is usually employed to cool core of long cylindrical products.
- Q.11 How many plates in the mould for transfer moulding process (three or four)?
- Q.12 _____ and _____ are the main elements of mould.

SECTION-C

Note: Short answer type questions. Attempt any eight questions out of ten questions. (8x4=32)

- Q.13 Explain multi manifold die for co extrusion films.
- Q.14 Explain heating and temperature control systems for dies.
- Q.15 Discuss parison programming and control.
- Q.16 Explain positive type compression mould.
- Q.17 Explain die land and die swell.
- Q.18 Discuss calculations for clamp pressure for compression mould.