

No. of Printed Pages : 4
Roll No.

MSIL-121734/031734

3rd Sem / Mech. Engg. (MSIL)
Sub : Machine Drawing

Time : 3Hrs.

M.M. : 100

SECTION-A

Note: Objective type questions. All questions are compulsory (10x2=20)

Q.1 Define bilateral limits.

Q.2 Define clearance fit?

Q.3 Define hole basis system of fit.


Q.4 Why universal coupling is used?

Q.5 Draw the convention of threaded inserts.

Q.6 What is function of socket and spigot joint?

Q.7 Name the bearing used to support vertical shaft?

Q.8 Name any two types of Gear.



- Dimension units may be taken in mm.
- Assume suitable dimension as required if not specified or not visible clearly in the given figures.

Q.9 What is the use of Fast & Loose pulley.

Q.10 Write the main function of piston in IC engine

SECTION-B

Note: Long answer type questions. Attempt any four questions out of five questions. (20x4=80)

Q.11 Draw the free hand sketch of screw jack.

Q.12 Draw the free hand sketch of expansion pipe joint.

Q.13 Draw the free hand sketch of piston of four stroke petrol engine.

Q.14 Fig 1 shows the detail drawing of foot step bearing. Draw the following assembled views :

- Front view full in section
- Top view




Figure1. Detail drawing of foot step bearing

- Dimension Units may be taken in mm.
- Assure suitable dimension as required if not specified or not visible clearly in the given figure.

Q.15 Fig. 2 shows the detail drawing of drill jig. Draw the following assembled views :

- Front view full in section
- Top view