

- Q.26 Define broaching tool. Draw its labeled diagram.
 Q.27 Write the factors in selecting broaching machine.
 Q.28 Explain the sources of heat during metal cutting.
 Q.29 Name the types of lathe machine. Explain anyone.
 Q.30 Classify drilling machines.
 Q.31 Explain the working principle of boring with suitable diagram.
 Q.32 Explain the working of jig boring machine with diagram.
 Q.33 Explain any five characteristics of a good lubricant.
 Q.34 Write the functions of cutting fluid.
 Q.35 Explain the principle of location.

SECTION-D

- Note:** Long answer type questions. Attempt any two questions out of three questions. (2x10=20)
 Q.36 Describe a tool with 8, 10, 5, 5, 6, 6, 1 signature. Explain the significance of tool signature.
 Q.37 Explain any five lathe operations with diagram.
 Q.38 Draw the labeled of twisting drill. Explain important parts.

No. of Printed Pages : 4 MSIL-121744/031744
 Roll No.

4th Sem / Mech. Engg. (MSIL) Sub : Workshop Technology-II

Time : 3Hrs.

M.M. : 100

SECTION-A

Note: Multiple choice questions. All questions are compulsory (10x1=10)

- Q.1 Milling cutter is a
 a) Multipoint cutting tool
 b) Single point cutting tool
 c) Reciprocating tool
 d) None of these
- Q.2 The percentage of chromium is 18-4-1 high speed steel is
 a) 18% b) 4%
 c) 1% d) 0%
- Q.3 In lathe machine, the tool post is mounted on
 a) Compound rest b) Head stock
 c) Tail stock d) Bed
- Q.4 The machine used in turning operation is
 a) Lathe b) Planer
 c) Shaper d) Slotter

- Q.5 In boring machine
- The job rotates
 - The tool rotates
 - Both tool & job rotates
 - None
- Q.6 A cutting fluid should be
- Chemically stable
 - Non corrosive
 - Suitable for variety of cutting tools
 - All correct
- Q.7 Which of the following is not solid lubricant?
- Graphite
 - Zinc Oxide
 - Grease
 - Both (a) & (b)
- Q.8 Jigs are used to
- Fix the work piece
 - Guide the tool
 - Vibrate the workpiece
 - Both (a) & (b)
- Q.9 Which of these is not a part of a shaper?
- Ram
 - Tail stock
 - Tool head
 - Clapper box
- Q.10 In lathe machine
- The job rotates
 - The tool rotates
 - Both tool & Job rotates
 - None

(2) MSIL-121744/031744

SECTION-B

Note: Objective type questions. All questions are compulsory. (10x1=10)

- Q.11 Define Feed in drilling operation.
- Q.12 Define Tool signature.
- Q.13 Define shaper machine.
- Q.14 Define Knurling Process.
- Q.15 Define Reaming process.
- Q.16 Define Locating devices.
- Q.17 Define Ceramics.
- Q.18 Define Lubrication process.
- Q.19 Define Boring.
- Q.20 Define Head stock.

SECTION-C

Note: Short answer type questions. Attempt any twelve questions out of fifteen questions. (12x5=60)

- Q.21 Write the working principle of shaper.
- Q.22 Write any four differences between shaper and planer.
- Q.23 Write any four properties of cutting tool material.
- Q.24 Name various types drills. Explain anyone.
- Q.25 Enlist various cutting parameters in lather machine. Define any two.

(3) MSIL-121744/031744