

- Q.24 Safe operating practices in forging hammer
- Q.25 Test of abrasive disks and wheels
- Q.26 Safety in ladle handling
- Q.27 Hazards associated with electroplating
- Q.28 Care in the use of hoses and hose connections in gas welding.
- Q.29 Safety Precautions in Resistance Welding.
- Q.30 Hazards associated in Spray painting.
- Q.31 Describe types of steel
- Q.32 Hazards and safety measures in high speed steel salt bath.
- Q.33 Safety in Metal Shears
- Q.34 Safety measures in handling of Dies in Forge Shop
- Q.35 Safety in wire drawing operations.

SECTION-D

- Note:** Long answer type questions. Attempt any two questions out of three questions. (2x10=20)
- Q.36 Discuss the hazards and safety measures in Arc Welding and cutting.
 - Q.37 Explain the Hazards and Safety measures in the use of Boring Machines & Milling Machines.
 - Q.38 Discuss the hazards and safety measures of bending machine.

No. of Printed Pages : 4
Roll No.

RLI-095408A

1st Year / Industrial Safety Subject:- Safety in Engineering Industries

Time : 3Hrs.

M.M. : 100

SECTION-A

Note: Multiple choice questions. All questions are compulsory (10x1=10)

- Q.1 During hot working of metals
 - a) porosity of the metal is largely eliminated
 - b) grain structure of the metal is refined
 - c) mechanical properties are improved due to refinement of grains
 - d) all of the above
- Q.2 Why is proper ventilation crucial in welding areas?
 - a) To keep the area warm
 - b) To remove welding fumes and gases
 - c) To create a pleasant working environment
 - d) To reduce noise levels
- Q.3 The Chapter IV of the factories Act, 1948 deals on the following safety
 - a) Provisions relating to hazardous processes
 - b) Welfare
 - c) None of the above
- Q.4 Which of the following hazards presence in the foundry is responsible for lung disease to the workers?
 - a) Noise
 - b) Metal splashes
 - c) Heat
 - d) Dust

- Q.5 In electrical safety, what does “arc flash” refer to?
- A type of welding technique
 - An electric shock caused by lightning
 - A dangerous release of energy caused by an electrical arc
 - A short circuit in electrical systems
- Q.6 The main purpose of a grinding wheel guard is to,
- Limit grinding to a small part of the wheel
 - Protect the operator from flying spark
 - Prevent pieces from being thrown from a broken grinding wheel
 - All of the above
- Q.7 Most accidents in grinding operations occur due to _____
- Improper grinding wheels
 - Poor maintenance of grinding machines
 - Improper storage of grinding wheels
 - All of the above
- Q.8 Which of the following is not an example of a finishing process?
- grinding
 - broaching
 - lapping
 - honing
- Q.9 Safety precaution(s) while using torches is/are
- Set the regulator to the recommended pressure
 - Keep the blow pipe nozzle near to source of ignition
 - Both (a) and (b)
 - None of the above
- Q.10 Which type of force is applied through die in forging operation
- Tensile
 - Shear
 - Compressive
 - twisting

(2)

RLI-095408A

SECTION-B

Note: Objective type questions. All questions are compulsory. (10x1=10)

- Q.11 Full form of MIG welding.
- Q.12 _____ is a process of heat treating, which is used to increase the toughness of iron-based alloys
- Q.13 A _____ degree burn causes the skin to blister.
- Q.14 Write full form of 5S.
- Q.15 A butane or propane cigarette lighter is safe around welding equipment as long as it is kept in one's pocket. (True/False)
- Q.16 While performing ring test tapping of wheel is done gently with _____ mallet.
- Q.17 _____ is a long-term lung disease caused by inhaling large amounts of crystalline silica dust.
- Q.18 A first degree burn is the most serious classification. (True/False)
- Q.19 The function of Primary Clarifier is to remove suspended heavy particles from the raw effluent. (True/False)
- Q.20 Operator must stay with the machine after the power button has been turned off and the blade has come to a complete stop. (True/False)

SECTION-C

Note: Short answer type questions. Attempt any twelve questions out of fifteen questions. (12x5=60)

- Q.21 Flow chart foundry industry.
- Q.22 Difference between hot and cold process
- Q.23 Working of blast furnace.

(3)

RLI-095408A