

- Q.22 How Strength of ware changes with porosity ?
Explain.
- Q.23 Tell function of lubricant. Give two examples.
- Q.24 Tell function of deflocculants. Give two examples.
- Q.25 How green density changes with increases with pressure.
- Q.26 Explain injection moulding.
- Q.27 List any five functions of binder.
- Q.28 Name control employed in press department.
- Q.29 Explain how will you determine post pressing expansion.
- Q.30 Explain tape casting process.
- Q.31 Explain development of electrical double layer.
- Q.32 Differentiate alpha and beta plaster of paris.
- Q.33 Explain Ceramic laboratory hazards.
- Q.34 Explain how viscosity of slip or glaze is determined in production control.
- Q.35 Explain upstream measures to reduce pollution.

SECTION-D

- Note:** Long answer type questions. Attempt any two questions out of three questions. (2x10=20)
- Q.36 Define casting. List its types. Explain slip casting methods of hollow ware production in detail.
- Q.37 Explain different steps used to make plaster of paris moulds.
- Q.38 Explain production controls used in glazing department.

No. of Printed Pages : 4
Roll No.

180451

5th Sem / Ceramic Subject:- Ceramic Processing Technology

Time : 3Hrs.

M.M. : 100

SECTION-A

Note: Multiple choice questions. All questions are compulsory (10x1=10)

- Q.1 Physical state of mixed body in case of slip casting is _____
a) Fluid /slip suspension
b) Powder
c) Plastic mass
d) None of these
- Q.2 In isostatic pressing pressure is applied from _____ side/sides.
a) Two
b) One
c) All
d) None of these
- Q.3 _____ are the materials which are used to reduce the friction between metal die and powder during pressing.
a) Preservatives
b) Binders
c) Foaming agents
d) Lubricants
- Q.4 _____ controls are carried out for finished product.
a) Crazing Resistance
b) Abrasion Resistance
c) Bending strength
d) All of the above

- Q.5 Strength of article increases as the volume fraction of pores_____.
 a) Increases
 b) Decreases
 c) Remain same
 d) First increases then decreases.
- Q.6 Thermal shock resistance decreases with an_____ in percentage pore volume
 a) Increases
 b) Decreases
 c) Remain same
 d) First increases then decreases
- Q.7 _____ in approximate moisture content in dry powder.
 a) 10-20% b) 25-50%
 c) 0-5% d) All of above
- Q.8 After ejection of pressed shaped ware size of piece_____
 a) Increases
 b) Decreases
 c) Remain same
 d) First increases then decreases
- Q.9 Example of deflocculant is
 a) Polyvinyl Alcohol
 b) Carboxy Methyl Cellulose
 c) Starches
 d) Sodium Silicate
- Q.10 _____ are used to prevent degrading of organic binders.
 a) Foaming Agents b) De foaming agents
 c) Preservatives d) Lubricants

SECTION-B

Note: Objective type questions. All questions are compulsory. (10x1=10)

- Q.11 Approximate moisture content in slip is_____.
 (10-20%, 25-50%, 0-5%)
- Q.12 Bag filters are used to control _____ in gaseous emission.(Dust /Poisonous gas)
- Q.13 In single acting pressing pressure is applied from _____ sides. (single side/ Both side / All side)
- Q.14 With increases in moulding pressure green density _____. (Increases / Decreases)
- Q.15 Alpha plaster is prepared by calcinations in_____ atmosphere.(Damp/Dry)
- Q.16 _____ casting method does not involve plaster of paris moulds. (Tape /Hollow)
- Q.17 Firing shrinkage increases with increases in die pressure. (True/False)
- Q.18 Compaction ratio is the ratio of fill room height to_____.
- Q.19 While mixing of POP with water, water is added in POP. (True/False)
- Q.20 The difference in weight of tile before and after glazing gives applied weight of glaze.(True/False)

SECTION-C

Note: Short answer type questions. Attempt any twelve questions out of fifteen questions. (12x5=60)

- Q.21 Tell two types of casting. Explain any one.