

- Q.24 Draw neat sketch of Hand injection moulding explaining its parts.
- Q.25 Explain Location and guide system mechanism for injection moulds.
- Q.26 Write short note on:
a) Positive mould b) flash mould
- Q.27 Discuss 'encapsulation' process.
- Q.28 Give importance of preheating moulds, in moulding process.

SECTION-D

- Note:** Long answer type questions. Attempt any two questions out of three questions. (2x25=50)
- Q.29 Design and draw a hot runner mould for car Head lamps, assume suitable dimensions.
- Q.30 Design and Draw a multi cavity semi positive type mold for an electrical Switch (Assume Suitable dimensions)
- Q.31 Design and Draw a multi cavity Injection mould for plastic comb with suitable dimensions.

No. of Printed Pages : 4
Roll No.

181852/121852/031852

5th Sem / T&D Subject:- Plastic Mould Design and Drawing

Time : 3Hrs.

M.M. : 100

SECTION-A

Note: Multiple choice questions. All questions are compulsory (10x1=10)

- Q.1 In compression molding, the curing time does not depend on which of the following factors?
a) Material b) Curing temperature
c) Geometry d) Thickness
- Q.2 Complex shape of parts or components cannot be formed by the injection moulding process.
a) True b) False
- Q.3 Which of the following processes of moulding is widely used for the manufacturing of bottle caps and automotive dashboards?
a) Compression moulding
b) Transfer moulding
c) injection moulding
d) Jet moulding
- Q.4 What is the maximum curing time required in a compression molding process?
a) 2 minutes b) 3 minutes
c) 4 minutes d) 5 minutes

- Q.5 Core gives internal shape to plastic part.
 a) True b) False
 c) Maybe d) None of above
- Q.6 Sprue pins are tapered so that _____
 a) Sprue pattern can be removed easily
 b) Surface can be smoothen easily
 c) The pins can be removed easily
 d) None of these
- Q.7 In compression moulding the curing time is _____.
 a) Less b) Moderate
 c) More d) None
- Q.8 Identify the product that can be not made by compression moulding process.
 a) Automotive panels
 b) Washing machine housing
 c) Bottles
 d) Gaskets
- Q.9 The distance between the stationary platen and the moving platen on a molding press when the actuating system is fully retracted without ejector box and/or spacers.
 a) Mold Height b) Machine Height
 c) Daylight d) None of these
- Q.10 What is the ideal material for processing in compression moulding?
 a) Plastics
 b) Thermoplastics
 c) Thermo setting plastics
 d) Non Ferrous materials

SECTION-B

Note: Objective type questions. All questions are compulsory. (10x2=20)

- Q.11 Vents are provided for easy removal of entrapped air inside mould. (True/False)
- Q.12 Mould closing and opening depends on size of the component. (True/False)
- Q.13 Give two functions of band heaters.
- Q.14 _____ process is associated with breathing.
- Q.15 What is injection pressure?
- Q.16 What do you meant by clamping force?
- Q.17 Name two types of ejector grid.
- Q.18 What are the types of injection mold?
- Q.19 Size of the gate should be kept _____ for better design.
- Q.20 Sharp edges in the die are created by _____ machine.
- Q.21 What are sliders?
- Q.22 What is flash mould?

SECTION-C

Note: Short answer type questions. Attempt any four questions. (5x4=20)

- Q.23 Discuss mould for threaded components.