

- 182244

Time : 3 Hrs.

M.M. : 100

SECTION-A

- Note:** Multiple choice questions. All questions are compulsory (10x1=10)

- Q.1 ASTM Code for tear testing of plastics is _____.
a) D638 b) D570
c) D1004 d) D665
- Q.2 ISO stands for _____.
a) Indian society organization
b) Indian standard Organization
c) Institute of standardization
d) None of the above
- Q.3 BIS stands for _____.
a) Bureau of Indian Standards
b) Basic of Indian Standards
c) British International Standards
d) None of these
- Q.4 _____ gives fruity smell when burn.
a) PE b) PP
c) PMMA d) PET

- Q.5 ASTM D1238 is the standard for _____ test.
 a) Tensile test b) Flexural test
 c) Flame test d) MFI
- Q.6 Which plastic material softened on heating but does not drips.
 a) HIPS b) PVA
 c) ABS d) All of these
- Q.7 ASTM D790 is the standard for _____ test.
 a) Tensile test b) Flexural test
 c) Flame test d) MFI
- Q.8 WVT stands for _____.
 a) Waste vapour test
 b) Water vapour transmission
 c) Water value test
 d) None of these
- Q.9 MFI value indicated in _____.
 a) g/1min b) g/100 min
 c) g/10min d) None of these
- Q.10 Creep is a _____ dependent phenomenon.
 a) Temperature b) Time
 c) Load d) Stress cycle

SECTION-B

Note: Objective/ Completion type questions. All questions are compulsory. (10x1=10)

- Q.11 Expand DIN.
 Q.12 ASTM D792 is the standard test number for _____ test.

(2)

182244

- Q.13 PMMA burns with _____ flame.
 Q.14 The needle in VSP test penetrates to _____ mm is specimen.
 Q.15 DSC stands for _____.
 Q.16 Which type of flame is observed when Polyvinyl chloride burns?
 Q.17 Name 6 sigma parameters.
 Q.18 TGA stands for _____.
 Q.19 Polystyrene gives _____ sound when dropped.
 Q.20 PVC gives _____ odour, when burned.

SECTION-C

Note: Short answer type questions. Attempt any twelve questions out of fifteen questions. (12x5=60)

- Q.21 Explain fatigue bending test.
 Q.22 Discuss preconditioning of specimen preparations for plastic testing.
 Q.23 Discuss water absorption test.
 Q.24 Explain Rockwell hardness and Brinell hardness test.
 Q.25 Discuss Charpy impact strength test.
 Q.26 Discuss various visual identification techniques of plastic giving suitable examples.
 Q.27 Explain Heat distortion temperature.
 Q.28 Explain thermal conductivity test for plastics.
 Q.29 Discuss milling, punching and templates techniques for plastic specimen preparation.
 Q.30 Discuss Six-Sigma technology of quality control.
 Q.31 Explain tear test.

(3)

182244