

- Q.6 Which one is NOT an angular measuring instrument?
- a) Bevel protractor b) Combination set
c) Screw pitch gauge d) Surface plate
- Q.7 A snap gauge is used to measure:
- a) Length b) Angle
c) Diameter d) Surface finish
- Q.8 Allowance is:
- a) Unavoidable error
b) Intentional difference between hole & shaft size
c) Difference between maximum & minimum size
d) None of these
- Q.9 Surface finish symbol is represented on:
- a) Gear b) Drawing
c) Workpiece d) Gauge
- Q.10 Tool Maker's Microscope is used for:
- a) Checking profiles
b) Measuring temperature
c) Checking pressure d) Measuring weight

SECTION-B

Note: Objective type questions. All questions are compulsory. (10x1=10)

- Q.11 Write the definition of sensitivity.
Q.12 Write two types of comparators.
Q.13 Write one use of V-block.

- Q.14 Define the term concentricity.
Q.15 What is the use of ring gauge?
Q.16 Write two environmental factors affecting measurement.
Q.17 What is calibration of an instrument?
Q.18 Write one difference between quality control and quality assurance.
Q.19 Define the term waviness in surface finish.
Q.20 Expand CMM.

SECTION-C

Note: Short answer type questions. Attempt any twelve questions out of fifteen questions. (12x5=60)

- Q.21 Explain the scope and need of metrology.
Q.22 Differentiate between sensitivity and repeatability.
Q.23 Explain principle and working of vernier caliper.
Q.24 Classify error in measurement with examples.
Q.25 Write a short note on feeler gauge.
Q.26 Explain the use of bevel protector.
Q.27 Explain how circularity and cylindricity are checked.
Q.28 Define interchangeability and selective assembly.
Q.29 Write short note on plain plug gauge.