KaiOS Jio 2.5 quoin Release Note

Date Release non-KaiOS APP tag for JIO Qwerty phone non-KaiOS APP tag for JIO Candy Bar phone Type 3-15-2019 kaios_jio_quoin_2_5_20181106_R3_ER5_production jio_apps_2.5_230119_2.8_qwerty jio_apps_2.5_230119_2.9_candybar TA Candidate Release

Integration Dependencies

1. Integration based on Qualcomm Grease release AU_LINUX_GECKO_LF.BR.1.2.8.C2.00.00.000.106

2. [ODM - MANDATORY] Add Reverie RT9/QWERTY Library to manifest:

For candy bar

For awerty:

3. [ODM - Optional] Additional repo for MMI Test source is made available to ODMs:

4. [ODM - MANDATORY /NFC] For NFC Devices Add nfcd project from KaiOS:

revision="refs/tags/kaios_jio_quoin_2_5_20181106_R3_ER5_production"/>

5. [ODM] Needed for altering Jio Store server settings - add below project:

- 6. [ODM MANDATORY] Add Jio Sales Tracker from Adups (ODMs to get username & password from Adups):
- 6.1 clone project from Adups into external/sales-tracker/ directory:
- 1. Go to web: http://rgit.adups.com/customer/Sales_Tracker.git
- 2. Login with user name: odm (password is same as before)
- 6.2 add below line in device/qcom/common/common.mk:

\$(call inherit-product-if-exists, external/sales-tracker/sales-tracker.mk)

7. [ODM - MANDATORY] for Metrics Daemon:

7.1 Add two repositories in manifest

project name="metrics" path="services/metrics" remote="quoin"

revision="refs/tags/kaios_jio_quoin_2_5_20181106_R3_ER5_production"/>

cyroject name="rust-toolchain" path="prebuilts/rust" remote="quoin"

revision="refs/tags/kaios_jio_quoin_2_5_20181106_R3_ER5_production"/>

7.2 Take below system_core patch

https://github.com/kaiostech/platform_system_core/commit/c30d1b4202dccd4243755226085cb6eaecc8b86a

7.3 if RJIO requests to enable performance and usage data sharing, please change SHARE_PERF_USAGE in gaia/Makefile from 0 to 1 like below:

Share performance and usage data

SHARE PERF USAGE?=1

Notes

- 1. Launch log manager with *#*#0574#*#*
- 2. Launch MMITest app with *#2886#
- 3. Please contact NXP for release note and information on NFC_NClx_KRC0.2.11.0 release
- $4.\ revert\ api-daemon\ to\ commit\ https://git.kaiostech.com/quoin/api-daemon/commit/14cb78c04981d0 fea 6ebd3705f23 dec 28090901cto\ fix\ bug57083$
- 5. revert patch of bug44287 and bug50171 to remove 2000 contacts sync limitation and fix bug57502/51303

ODM Config		
Model Name	ro.product.model	
KaiOS version	ro.product.version_tag = kaios_jio_quoin_2_5_20181106_R3_ER5_production	
ODM version	ro.build.version.incremental	
Chipset version	ro.product.base_version	
SAR Value	ro.product.sar_value e.g. ro.product.sar_value=1.23	
Network types UI	ro.moz.ril.0.network_types e.g. ro.moz.ril.0.network_types=gsm,wcdma,lte	
Torch LED	ro.kaios.torch_node=/sys/class/leds/flashlight/brightness ro.kaios.torch_enable_value=127	

Enable NFC	Include NXP/KaiOS projects set ro.moz.nfc.enabled = true
	2. Set 10.11102.1116.eHable0 = true
	deviceinfo.cu needs to be defined in/gaia/distribution/settings.json;
CU Reference (Please consult Jio)	Please check with Reliance JIO team on the value of CU Reference, in general, it is same as CU Ref used by FOTA which means deviceinfo.cu shares same value as ro.fota.cu_ref;
	+ "deviceinfo.cu" : "XXXX-YYYZZZ",
	ro.fota.cu_ref:
KaiOS FOTA Parameters (Please consult Jio)	ro.fota.sw_ver: ro.fota.SUMaster: ro.fota.network_type:
	ro.fota.network_port: (default 80)
	Please kindly get associated FOTA diff tool from git server which is under/fota_tools; If BLOCK FOTA is needed, the version information of FOTA diff tool is under/fota_tools/BLOCK/tools_version.sh and the version for this release is v1.6.0 which full update the bootloader image(sbl1, tz, rpm, aboot) if they are different between source and taget;
KaiOS FOTA diff tool	Taking BLOCK FOTA diff tool as an example, following steps can be used to make full modem diff package:
	put source and target softwares into softeware/src and softeware/tgt then run ./prepare_pkg_start.sh and ./gen_update_pkg_start.sh
	Create a new directory under device directory with the name "default-prefs" (e.g. /device/qcom/msm8909_512)
Device Pref (see options below)	2. created a new file name "dev-pref.js" inside the directory "default-prefs" Add below preferences into this file
	3. In the Device mk file (e.g. device/qcom/msm8909_512/msm8909_512.mk) add EXPORT_DEVICE_PREFS line: e.g. EXPORT_DEVICE_PREFS := /device/qcom/msm8909_512/default-prefs
Browser UA String	<pre>pref("general.useragent.use_device", true); pref("general.useragent.device_string", "[Device String]");</pre>
Internal FM Antenna	pref('dom.fmradio.antenna.internal', true);
Jio Push Server	pref("dom.push.serverURL", "wss://push.kai.jiophone.net:443/");
IPv6	If JIO requests to turn on IPv6 tethering, please add new flag in makefile such as/msm8909_512.mk as: # Enable IPv6 tethering
ViLTE (IR94)	ENABLE_RADVD := true If JIO requests to turn on or off IR94, please go to/dev-pref.js and set following flag as true or
VIETE (ITO+)	false accordingly: device.capability.vilte turn off by default as per RJIO request in ticket 43670 comment 20
VoWiFi (IR51)	If JIO requests to turn on or off IR51, please go to/dev-pref.js and set following flag as true or false accordingly: device.capability.vowifi turn off by default as per RJIO request in ticket 43670 comment 31
eMBMS	
	1. The board config "TARGET_ENABLE_EMBMS" can only be configured by Kai, default is TRUE. 2. The pref "dom.embms.enabled" is proposed to work as a confirming toggle for OEMs to disable EMBMS on demand in case "TARGET_ENABLE_EMBMS" is true in prebuilt gecko. Here is the code piece of b2g/app/b2g.js: // Disable eMBMS by default. +#ifdef ENABLE_EMBMS
	+pref("dom.embms.enabled", false); +#endif If OEM doesn't get source from KaiOS, please toggle pref "dom.embms.enabled" in proc- prefs.js or dev-pref.js file instead of b2g.js. ex: in /device/qcom/msm8909_512/default- prefs/proc-prefs.js, put pref("dom.embms.enabled", true); 3. If "TARGET_ENABLE_EMBMS" is false, EMBMS will be definitely disabled regardless of the value of "dom.embms.enabled".

Please add pref("device.capability.qwerty", rue) and APP developer can use code su as "navigator has Featurer" (device.capability.qwerty") == true" to know that current deviunder landscapeperode; Please set "orientation": "landscape-primary" in the manifest.webapp of concerned wisich as MMIT est module; Please add ENABLE, REVERIE, QWERTY := true to board config makefile; Please add pref("device.capability.endcall-key", true) to/dev-pref.js; pref("device.capability.endcall-key", true) be added to/dev-pref.js as by default setting deverty; Please add following new proprety to board config makefile, each hardware has its ownoringfile such as device.ecom/msm8005_512mms.pease check with supplier on which board is used for this project; + persist.radio.multisin.config=dsds Please kindly check with Reliance JIO whether SIM1 needs to be fixed as JIO SIM on only and SIM2 need to be fixed as GSM only, if so, please set - ro.moz.rifl.onework_types=gsm.wcoma.tte + ro.moz.rifl.nework_types=gsm.wcoma.tte **To.moz.rifl.nework_types=gsm** If api-dameon needs to be turn-on per the request of JIO, please kindly: 1. please make sure that following two git repositories has been correctly synchronize on manifest: - project name-"api-daemon" path-"services/api-daemon"/> project name-"api-daemon" path-"services/api-daemon"/> project name-"ad-scide, "path-"services/api-daemon"/> project name-"ad-scide, "path-"services/api-daemon"/> project name-"ad-scide, "path-"services/api-daemon /system.kaios.config.toml class main user root 4. please check that QCOM code,/system/core/libcutitis/fs_config.c, includes following user root 4. please one, DM can check with QCOM if ODM would like to understand how new t process can be added to system SW. By 93-90.0m, QMT+3, May, 18, 2018, reference developed by QCOM for this purpose can be found on Code/aurora at https://source.codeaurora.org/api-daemon/system.core/are/fibcutitis/fs_config.do. 1f ODM needs to display HW version by phone Ut to end user, ODM can add one	are has se check
such as MMITest module; Please add ENABLE_REVERIE_OWERTY:— true to board config makefile; Please add pref("device.capability.endcall-key", true) to/dev-pref.js; pref("device.capability.endcall-key", true) be added to/dev-pref.js as by default settir	
Please add pref("device.capability.endcall-key", true) to/dev-pref.js; pref("device.capability.endcall-key", true) be added to/dev-pref.js as by default setti qwerty; Please add following new proprety to board config makefile, each handware has its ow configfile such as device/qcom/msm8909_512/msm8909_512.mk, please check with supplier on which board is used for this project; +persist.radio.multisim.config=dsds Please kindly check with Reliance JIO whether SIM1 needs to be fixed as JIO SIM on only) and SIM2 need to be fixed as GSM only, if so, please set -ro.moz.ril.0.network. types=gsm,wcdma,lte +ro.moz.ril.0.network. types=gsm If api-dameon needs to be turn-on per the request of JIO, please kindly: 1, please make sure that following two git repositories has been correctly synchronize on manifest: -project name="api-daemon" path="services/api-daemon"/> -project name="api-daemon" path="services/api-daemon"/> -project name="adi-sak" path="services/api-daemon adi-sak"/> -project name="adi-sak" path="services/api-daemon adi-sak"/> -project name="adi-sak" path="services/api-daemon"/> -project name="adi-sak" path="services/api-daemon"/> -project name="adi-sak" path="services/api-daemon"/> -project name="adi-sak" path="services/api-daemon adi-sak"/> -project name="adi-sak" path="services/api-daemon"/> -project name="adi-sak" path="	b APP
pref("device.capability.endcall-key", true) be added to/dev-pref.js as by default setting the control of the	
Dual SIM Please add following new proprety to board config makefile, each hardware has its ow configfile such as device/cgom/msm8090_512/msm8909_512.mk, please check with supplier on which board is used for this project; +persist_radio.multisim.config=dsds Please kindly check with Reliance JIO whether SIM1 needs to be fixed as JIO SIM on only) and SIM2 need to be fixed as GSM only, if so, please set - ro.moz.rii.0.network_types=gsm.wcdma,tte + ro.moz.rii.1.network_types=gsm.wcdma,tte + ro.moz.rii.1.network_types=gsm If api-dameon needs to be turn-on per the request of JIO, please kindly: 1. please make sure that following two gir repositories has been correctly synchronize on manifest: https://dameo.org/linetwork_types=gsm If api-dameon needs to be turn-on per the request of JIO, please kindly: 1. please make sure that following two gir repositories has been correctly synchronize on manifest: https://dameo.org/linetwork_types=gsm If api-dameon needs to be turn-on per the request of JIO, please kindly: 1. please make sure that following two gir repositories has been correctly synchronize on manifest: https://dameo.org/linetwork_types=gsm If api-dameon needs to be turn-on per the request of JIO, please kindly: 1. please manifest: https://dameo.org/linetwork_types=gsm If api-dameon needs to be turn-on per the request of JIO, please kindly: 2. KaiOS adds following line of code to ./gonk-misc/b2g.mk and ODM can double the PRODUCT_PACKAGES += api-daemon /system/kaios/config.comicals smain user root 4. please check that OCOM code, ./system/core/libcutils/fs_config.c, includes following line of code to ./gonk-misc/b2g.mk and ODM can developed by Dameo. Api-daemon /system/kaios/api-daemon /system/kaios/api-daemon /system/kaios/api-daemon /system/kaios/api-daemon /system/kaios/api-daemo	
configitie such as device/igcom/msm8909_512/msm8909_512.mk, please check with supplier on which board is used for this project; +persist.radio.multisim.config=dsds Please kindly check with Reliance JIO whether SIM1 needs to be fixed as JIO SIM on only) and SIM2 need to be fixed as GSM only, if so, please set -ro.moz.rii.0.network_types=gsm,wcdma.lte +ro.moz.rii.0.network_types=lle +ro.moz.rii.1.network_types=gsm If api-dameon needs to be turn-on per the request of JIO, please kindly: 1. please make sure that following two git repositories has been correctly synchronize on manifest: -project name="api-daemon" path="services/api-daemon"/> -project name="ads-sdk" path="services/api-daemon ads-sdk"/> 3. KaiOS adds following line of code to/gonk-misc/init.b2g.rc and ODM can double service api-daemon /system/kaios/api-daemon /system/kaios/config.toml class main user root 4. please check that QCOM code,/system/core/libcutils/fs_config.c, includes following low/formal path path path path path path path path	g in
Please kindly check with Reliance JIO whether SIM1 needs to be fixed as JIO SIM on only) and SIM2 need to be fixed as GSM only, if so, please set -ro.moz.ril.O.network_types=gsm,wcdma,lte + ro.moz.ril.1.network_types=glen + ro.moz.ril.1.network_types=gsm If api-dameon needs to be turn-on per the request of JIO, please kindly: 1. please make sure that following two git repositories has been correctly synchronize on manifest: - cyreject name="api-daemon" path="services/api-daemon"/> - cyreject name="api-daemon" path="services/api-daemon"/> - cyreject name="ads-sdk" path="services/ads-sdk"/> 2. KaiOS adds following line of code to ./gonk-misc/b2g.mk and ODM can double che PRODUCT_PACKAGES += api-daemon ads-sdk 3. KaiOS adds following line of code to ./gonk-misc/init.b2g.rc and ODM can double service api-daemon /system/kaios/api-daemon /system/kaios/api-daemon /system/kaios/api-daemon lass main user root 4. please check that QCOM code, ./system/core/libcutils/fs_config.c, includes following {00775, AID_ROOT, AID_ROOT, 0, "system/kaios/api-daemon"}, Please note, ODM can check with QCOM if ODM would like to understand how new to process can be added to system SW. By 09:00am, GMT+8, May, 18, 2018, reference developed by QCOM for this purpose can be found on CodeAurora at https://source.codeaurora.org/quicta/platform/system/core/tree/libcutils/fs_config.c?h 2.8.c2-06900-8x09.0#n114, ODM can check with QCOM if further clarification is need to the process can be stored to display HW version by phone UI to end user, ODM can add one new property as listed as following to makefile, please note, string length of HW version new property as listed as following to makefile, please note, string length of HW version new property as listed as following to makefile, please note, string length of HW version new property as listed as following to makefile, please note, string length of HW version new property as listed as following to makefile, please note, string length of HW version new property as listed as following to make	
only) and SIM2 need to be fixed as GSM only, if so, please set - ro.moz.ril.0.network_types=gsm,wcdma,lte + ro.moz.ril.0.network_types=lte + ro.moz.ril.1.network_types=lte + ro.moz.ril.1.network_types=gsm If api-dameon needs to be turn-on per the request of JIO, please kindly: 1. please make sure that following two git repositories has been correctly synchronize on manifest: - project name="api-daemon" path="services/api-daemon"/> - cproject name="ads-sdk" path="services/ads-sdk"/> 2. KaiOS adds following line of code to/gonk-misc/b2g.mk and ODM can double ch PRODUCT_PACKAGES += api-daemon ads-sdk 3. KaiOS adds following line of code to/gonk-misc/init.b2g.rc and ODM can double service api-daemon /system/kaios/api-daemon /system/kaios/config.toml class main user root 4. please check that QCOM code,/system/core/libcutils/fs_config.c, includes following {00775, AID_ROOT, AID_ROOT, 0, "system/kaios/api-daemon"}, Please note, ODM can check with QCOM if ODM would like to understand how new be process can be added to system SM. By 09:00am, GMT-8, May, 18, 2018, reference developed by QCOM for this purpose can be found on CodeAurora at https://source.codeaurora.org/quic/la/platform/system/core/tree/libcutils/fs_config.c?h	
## ro.moz.ril.1.network_types=gsm If api-dameon needs to be turn-on per the request of JIO, please kindly: 1. please make sure that following two git repositories has been correctly synchronize on manifest: <pre></pre>	/ (LTE
If api-dameon needs to be turn-on per the request of JIO, please kindly: 1. please make sure that following two git repositories has been correctly synchronize on manifest:	
1. please make sure that following two git repositories has been correctly synchronize on manifest: <pre></pre>	
1. please make sure that following two git repositories has been correctly synchronize on manifest: <pre></pre>	
2. KaiOS adds following line of code to/gonk-misc/b2g.mk and ODM can double che PRODUCT_PACKAGES += api-daemon ads-sdk 3. KaiOS adds following line of code to/gonk-misc/init.b2g.rc and ODM can double of service api-daemon /system/kaios/api-daemon /system/kaios/config.toml class main user root 4. please check that QCOM code,/system/core/libcutils/fs_config.c, includes following { 00775, AID_ROOT, AID_ROOT, 0, "system/kaios/api-daemon" }, Please note, ODM can check with QCOM if ODM would like to understand how new Leave process can be added to system SW. By 09:00am, GMT+8, May, 18, 2018, reference developed by QCOM for this purpose can be found on CodeAurora at https://source.codeaurora.org/quic/la/platform/system/core/tree/libcutils/fs_config.c?h .2.8.c2-06900-8x09.0#n114, ODM can check with QCOM if further clarification is need to the property as listed as following to makefile, please note, string length of HW version need to the property as listed as following to makefile, please note, string length of HW version need to the property as listed as following to makefile, please note, string length of HW version need to the property as listed as following to makefile, please note, string length of HW version need to the property as listed as following to makefile, please note, string length of HW version need to the property as listed as following to makefile, please note, string length of HW version need to the property as listed as following to makefile, please note, string length of HW version need to the property as listed as following to makefile, please note, string length of HW version need to the property as listed as following to makefile, please note, string length of HW version need to the property as listed as following to makefile, please note, string length of HW version need to the property as listed as following to makefile, please note, string length of HW version need to the property as listed as followed to the property as listed as followed to the property as listed as followed to	l based
service api-daemon /system/kaios/api-daemon /system/kaios/config.toml class main user root 4. please check that QCOM code,/system/core/libcutils/fs_config.c, includes followin { 00775, AID_ROOT, AID_ROOT, 0, "system/kaios/api-daemon" }, Please note, ODM can check with QCOM if ODM would like to understand how new L process can be added to system SW. By 09:00am, GMT+8, May, 18, 2018, reference developed by QCOM for this purpose can be found on CodeAurora at https://source.codeaurora.org/quic/la/platform/system/core/tree/libcutils/fs_config.c?h .2.8.c2-06900-8x09.0#n114, ODM can check with QCOM if further clarification is nee If ODM needs to display HW version by phone UI to end user, ODM can add one new property as listed as following to makefile, please note, string length of HW version nee	ck:
{ 00775, AID_ROOT, AID_ROOT, 0, "system/kaios/api-daemon" }, Please note, ODM can check with QCOM if ODM would like to understand how new L process can be added to system SW. By 09:00am, GMT+8, May, 18, 2018, reference developed by QCOM for this purpose can be found on CodeAurora at https://source.codeaurora.org/quic/la/platform/system/core/tree/libcutils/fs_config.c?h .2.8.c2-06900-8x09.0#n114, ODM can check with QCOM if further clarification is nee If ODM needs to display HW version by phone UI to end user, ODM can add one new property as listed as following to makefile, please note, string length of HW version ne	heck:
process can be added to system SW. By 09:00am, GMT+8, May, 18, 2018, reference developed by QCOM for this purpose can be found on CodeAurora at https://source.codeaurora.org/quic/la/platform/system/core/tree/libcutils/fs_config.c?h.2.8.c2-06900-8x09.0#n114, ODM can check with QCOM if further clarification is need for the company of th	g:
property as listed as following to makefile, please note, string length of HW version ne	code :LF.BR.1
property as listed as following to makefile, please note, string length of HW version ne	
+ ro.hardware=;	-
ODM hardware version For instance, ODM may set ro.hardware=ODM name_SKU name_DVTx as HW version	n;
Once the new system property is added and a clean SW build is done, end user can version from phone UI from Settings APP at "Settings -> Device Information -> More information -> Hardware Version";	nd HW

ODM phone ROM size	Please kindly add ROM size of device in Mbyte to device folder as preference; For instance, if ROM size is 4GByte, please add pref("device.storage.size", 4096); if ROM size is 512MByte, please add pref("device.storage.size", 512);
Enable Marionette for MTBF	If a SW build is needed for MTBF testing, please kindly: 1, use no production SW tag, for instance, TA2_R2, not TA2_R2_production; 2, make a userdebug build;
KaiOS API version	Please kindly double confirm with Reliance JIO on KaiOS API version and add one new preference to/dev-pref.js accordingly. In general, it should be v2.0 and if it is v2.0, the new added preference will be: + pref("app.kaiapi.version", "2.0")

	Inches Pined		
57000	Issues Fixed		
	[REG][Qwerty][DSDS][Call log]The Call information show SIM2 After SIM1 and SIM2 call same phone number		
	[Qwerty][DSDS][Call log]The Call information show SIM2 After SIM1 and SIM2 call same phone number		
	[Metrics] enable metrics as default		
	Data collector :: app usage information is not reported to Jio Background Service(JBS)/DC app consistently.		
51303	[Contacts]Frozen screen appears when importing to 2000 contact Device getting nanged and importing zoou+ contacts from Ginan/SD card, also shows wrong alert 3906 contacts		
57502	Device getting hanged after importing 2000+ contacts from Ginari/SD card, also shows wrong afert 3936 contacts		
57228	[CLMID-1150510] [VIT_F90M]: Facebook App is Not functional and pointer disappears after MT call is received		
	[CLMID-1150510] [VIT_F90M]: Facebook App is Not functional and pointer disappears after MT call is received		
56643	Intermittently ADUPS ST not working		
57093	[clmid-1150407][VIT_F90M]: Device hangs and becomes unresponsive while accept/decline MT call during video		
37063	download in whats'app		
49107	Ruppee Symbol launch Payment Screen. [CLM ID - 922331]		
44427	[PRD] Option to launch Camera with front camera by default		
56410	[Camera]Add camera front/rear choice for 'pick' activity.		
56841	JIO App tags for R3_ER4 release for QCOM		
Dependent Issues			
Following ti	ckets are needed by		
	[ViLTE / VoWIFI] VoWiFi Phonebook: Device shall display correct icons during call in status bar & call logs to		
	differentiate Normal call, VoLTE call, VoWiFi call [CLM ID-706225] => it needs QCOM release		
43562	AU_LINUX_GECKO_LF.BR.1.2.8.C2.00.00.000.106		
	[DATA] Hipri type state is incorrect when WIFI is on. => QCOM needs to release a patch as per bug47970 comment		
47970	115, as a follow up patch for bug37523		

	Known issue	
51387	[FM]There is no "add to favourite" after use preset radio	
56378	[FM]It is not fully displayed after add to favorite and rename station	