PT. YONGJIN JAVASUKA GARMENT

INTRUKSI KERJA QC

WORK INSTRUCTION OF QUALITY CONTROL


No .Dokumen : YJ-IK.WLD.0015
Tgl.Efektif : 22 October 2023
No. Revisi : 0
Halaman : 1




1. SO yang sedang jalan, harus berada di meja QC
SO who is running, must be at the QC table



5. Jika hasil check tidak sesuai SO, posisi , warna dan material yang di gunakan , maka Qc harus segera lapor kepada chief / supervisor
If the check results do not match the SO, position, color and material used, then Qc must immediately report to the chief / supervisor



2.Periksa Numbring, ukuran , dan bundle
Check the numbering, size, and bundle



6. Scan potongan yang sudah di cheking , dan buat surat jalan jika ada ganti rijek
Scan the pieces that have been checked, and make a travel document if there is a replacement riject




3. Lakukan pemeriksaan 100% atau pcs by pcs
Do a check 100% or pcs by pcs





4. Pengechekan Logo / OT menggunakan pattern di periksa secara rendom (atas tengah bawah)
Checking the Logo / OT using a pattern is checked randomly (top, bottom, middle)



7. Membuat laporan hasil checking dan deffect , dan di tanda tangan oleh (supervisor, manager , QA)
Make a report on checking results and defects, and sign it by (supervisor, manager, QA)