
PT. YONGJIN JAVASUKA GARMENT	**Intruksi Kerja - Proses Gelar & Potong** ***Working Instruction - Spreading & Cutting Process***	No. Dokumen : YJ-IK.CUT.0014 Tgl. Efektif : 25 Januari 2018 No. Revisi : 02 Halaman : 1 dari 1

1

Cek marker komponen, assort, size, item pastikan sesuai dengan apa yang akan dikerjakan, pastikan kalibrasi marker sesuai mulai dari lebar dan panjang marker, beri tanda dengan menggunakan krayon untuk memisahkan direksi/ arah assort dan size pada marker sebagai pananda

Check the component markers, assortment, size, make sure the items are suitable for what will be done, make sure the marker calibration is appropriate starting from the width and length of the marker, make a mark using a crayon to separate the direction/direction of the assortment and size on the marker as a guide

2



Periksa jenis kain yg akan digelar sudah benar (warna, konstruksi, dll). Pastikan bagiannya tidak tertukar (face or bottom side). scan barcode fabric untuk memastikan fabric tersebut sudah di proses, Pastikan proses relax sudah terlampaui. Pastikan diambil dari lot yg sama untuk satu PO/warna dari data shade lot.

Check that the type of fabric that will be held is correct (color, construction, etc.). Make sure the parts are not swapped (face or bottom side). scan the fabric barcode to ensure the fabric has been processed. Make sure the relax process has been completed. Make sure it is taken from the same lot for one PO/color from the shade lot data.

3




Catat panjang dan total layer kain pada report yang sudah di sediakan *"spreading assortment report"*. Pastikan kain yang digelar sudah rata baik bagian kiri/kanannya. Periksa total ketinggian kainnya.

Record the length and total layers of fabric in the report that has been provided "spreading assortment report". Make sure the fabric being spread is even on the left/right side. Check the total height of the fabric.

4




Proses cutting, lakukan pengecekan oleh QC cutting dan adm gelaran untuk membuat sticker dan berikan laporan hasil gelar, dan check *"landtek moisture level standar" dan* di sign oleh Supervisor cutting

Cutting process, check by QC cutting and adm mat to make stickers and provide a report on the results of the degree, and check the "standard landtek moisture level" and sign it by the cutting supervisor

5




Adm gelar mengeluarkan sticker sesuai cp yang tertera di cutplan untuk identitas potongan

Admin issues a sticker according to the CP listed on the cut plan for the identity of the cut

6



Proses cutting (pemotongan bahan), cutting harus berdasarkan per po dan per warna, untuk menghindari campur lot dalam 1 po, atau shading garment.

Cutting process, cutting should be based on by po and per color, to avoid mixing lot in 1 po, or shading garment