PT. YONGJIN JAVASUKA GARMENT	INSTRUKSI KERJA NEEDLE DETECTOR NEEDLE DETECTOR WORKING INSTRUCTIONS	No. Dokumen : YJ-IK.PSO.0007 Tgl. Efektif : 01 September 2018 No. Revisi : 00 Halaman : 1

Calibration 9 point 3 times a day

↓

Set sensitive level to standart max

↓

Pass garment into needle detector machine

↓

Record all passed garment into a report

1



Calibrate 3x a day

2




Setting sensitive level

3



Pass the garment to the detector machine

4



Record all garments that have passed through the machine