PT. YONGJIN JAVASUKA GARMENT

INSTRUKSI KERJA CUTTING PANEL QC AKURASI ATAS,TENGAH,BAWAH

WORKING INSTRUCTIONS FOR CUTTING PANEL QC ACCURACY UP, MIDDLE, DOWN

No. Dokumen	: YJ-IK.CUT.0018
Tgl. Efektif	: 02 November 2022
No. Revisi	: 01
Halaman	: 1 dari 1

1) Prepare a single pattern that has been signed and approved by the pattern department, QA according to buyer standards


2) If percentace of 1% of 30cm is 3mm, it means its still ok, because the seam is 1 cm, so there is still 7mm left. likewise with a percentace of 2% from 30cm. for the right and left seam 1cm if the shirinkage is 6mm with the right and 'left its still ok with 7mm each seam, if its more than 30cm you have to check the accuracy first because if the shirinkage is 1 % or 2 % it wont be in tolerance

3) Prepare the pieces and fabric patterns to be checked according to the Top, Middle and Bottom measurements. Cutting tolerance ± 1/8 inch (3mm)

4) AQL (Acceptable Quality Level) If one bundle finds shrinkage of more than 1/8 inch (defects) in large quantities the operator will check 100%

5) If the measurement results of the panel cut shrinkage/defects are more than standard and the cut is larger than the pattern, the operator must report to the QC supervisor or chief cutting officer to find a solution.


6) The finished piece is measured with a single pattern of top, middle, bottom accuracy, report the actual measurement results







1) Siapkan pola tunggal/single pattern yang sudah ditanda tangani dan disetujui oleh bagian departemen pattern ,QA sesuai dengan standar buyer






2) Kalau persentase 1% dari 30cm adalah 3mm artinya masih ok, karena seam nya 1 cm jadi masih ada sisa 7mm, begitupun dengan persentase 2% dari 30cm. Untuk seam kanan dan kiri 1cm kalau susutnya 6mm dengan bagian kanan dan kiri masih ok dengan seam masing-masing 7mm, jika lebih dari 30cm harus check accuracy terlebih dahulu karena jika susut 1% atau 2% itu tidak akan masuk dalam toleransi





3) Siapkan potongan kain dan pola yang akan di cek sesuai dengan ukuran/size Atas, Tengah dan Bawah **Toleransi potongan ± 1/8 inch (3mm)**





4) **AQL (*Acceptable Quality Level*)** Apabila dalam satu bundle menemukan susut lebih dari 1/8 inch (cacat) dalam jumlah yang banyak operator akan check 100 %





5) Jika hasil pengukuran potongan panel susut/ cacat lebih dari standar dan potongan lebih besar dari pattern maka operator harus melapor ke supervisor QC atau chief cutting untuk mencari solusi





6) Potongan yang telah selesai diukur dengan pola tunggal/single pattern akurasi atas ,tengah,bawah buat laporan hasil pengukuran aktualnya