PT. YONGJIN JAVASUKA GARMENT

INTRUKSI KERJA CEKING PANEL

Working Instruction Panel Checking

No. Dokumen	: YJ-IK.CUT.0012
Tgl. Efektif	: 25 Januari 2018
No. Revisi	: 02
Halaman	: 1 dari 1

The QC operator checks the bill to see what style and size will be worked on first

Pay attention to the symbol on the marker (O) to determine the part/section that is being checked for quality, check each part/section carefully. Panel checking 100%

Separate the rejected panels, put an "arrow" on the rejected part


Bundle the reject panel and provide a description of the rejected panel number

Record the number and type of damage in the “Cutting panel inspection report”

Insert the Reject Panel bundle that has been replaced in the space provided


Panels that have been checked are transferred to the loading rack for storage

1



Operator QC mengcheck bon/ obd schedule untuk melihat style dan size apa yang akan di kerjakan terlebih dahulu

2




Perhatikan syimbol pada marker (O) untuk menentukan part/ bagian yang di checking kualitas , checking dengan teliti setiap part/ bagian Panel checking 100%

3




Pisahkan panel yang reject, beri tanda “Panah” pada bagian yang di reject

4



Bundle panel reject dan beri keterangan nomor panel yang di reject

5



Catat jumlah dan jenis reject pada report *“Cutting panel inspection report"*

6



Masukan bundle Panel reject yang sudah di ganti pada tempat yang telah di sediakan

7



Panel yang sudah di cheking di transfer ke loading rak untuk penyimpanan

Terima kasih anda telah melakukan pekerjaan sesuai dengan standard operasional prosedure, S.O.P. Pastikan pekerjaan hari ini lebih baik dari kemarin