WORKING MANUAL	Section: SAMPLE ROOM	Proces: METAL DETECTOR

PROCEDURES

Calibrate hand detector 5 times a day with 2 point calibration method

↓

Set up the sensitivity level of detector machine to maximum level

↓

Checking the garment using hand detector

↓

Record all PASSED garment into daily passed garment metal detection report

1



Lakukan kalibrasi hand detector Detector 5 kali sehari (pagi, siang, dan sore) dengan metode 2 POINT

2




Setting dan tentukan tingkat sensitifitas mesin sesuai dengan standard

3



Ceking garment menggunakan hand detector

4



Catat semua garment yang LOLOS (PASSED) dalam passed garment metal detection report.

WORKING MANUAL	**Section:** SAMPLE ROOM	**Proces:** CONTAMINATED GARMENT VERIFICATION

PROCEDURES

Separate the contaminated garment in garment contaminated area

↓

Verify the contaminated garment to find the metal object by hand detector machine

↓

Attach metal object found in the report Needle Detection Log

↓

Re-scan the panel used hand detector to ensure no metal contamination

↓

Put the garment in RED BIN BOX if garment cannot be verified

1




Pisahkan garment yang terkontaminasi metal di tempat terpisah, JANGAN SAMPAI TERCAMPUR

2



Periksa garment yang terkontaminasi metal menggunakan hand metal detector dan cari objek metal sampai dapat

3



Tempelkan metal object pada laporan Needle detection log

4



Periksa kembali garment menggunakan hand detector untuk memastikan ada metal atau tidak.

5



Masukkan garment ke kotak RED BIN BOX jika metal object tidak bisa ditemukan dan garment masih terkontaminasi.