WORKING MANUAL

Section:
EMBROIDERY

Proces:
CONTAMINATED GARMENT VERIFICATION

PROCEDURES

Separate the contaminated panel in panel contaminated area

↓

Verify the contaminated panel to find the metal object by hand detector machine

↓

Attach metal object found in the report Needle Detection Log

↓

Re-scan the panel used hand detector to ensure no metal contamination

↓

Put the panel in RED BIN BOX if panel cannot be verified

1



Pisahkan panel yang terkontaminasi metal di tempat terpisah, JANGAN SAMPAI TERCAMPUR

2



Periksa panel yang terkontaminasi metal menggunakan hand metal detector dan cari objek metal sampai dapat

3



Tempelkan metal object pada laporan Needle detection log

4



Periksa kembali panel menggunakan hand detector untuk memastikan ada metal atau tidak.

5



Masukkan panel ke kotak RED BIN BOX jika metal object tidak bisa ditemukan dan panel masih terkontaminasi.

WORKING MANUAL	Section: EMBROIDERY	Proces: METAL DETECTOR

PROCEDURES

Calibrate hand detector 5 times a day with 2 point calibration method

↓

Set up the sensitivity level of detector machine to maximum level

↓

Checking the panel using hand detector

↓

Record all PASSED panel into daily passed panel metal detection report

1



Lakukan kalibrasi hand detector Detector 5 kali sehari (pagi, siang, dan sore) dengan metode 2 POINT

2



Setting dan tentukan tingkat sensitifitas mesin sesuai dengan standard

3



Ceking panel menggunakan hand detector

4



Catat semua panel yang LOLOS (PASSED) dalam passed panel metal detection report.