

STABILIZING THE BEAM CURRENT SPLIT RATIO IN TRIUMF's 500 MeV CYCLOTRON WITH HIGH LEVEL, CLOSED-LOOP FEEDBACK SOFTWARE

J.J. Pon, K.S. Lee, M.M. Mouat, T. Planche, P.J. Yogendran
TRIUMF, Vancouver, Canada

ABSTRACT

In the pursuit of progressively more stable beam currents at TRIUMF's 500MeV cyclotron there was a proposal to regulate the beam current split ratio for two primary beam lines with closed-loop feedback. Initial runs have shown promising results and have justified further efforts in that direction. This paper describes the software to provide the closed-loop feedback, and future developments.

INTRODUCTION

- Three beam lines are presently in use but there are plans for a new fourth beam line
- Extracting multiple beams is relatively straight forward
- Stabilizing the beam currents in multiple beam lines is challenging
- Rare isotope production requires stable beam current:
 - Too much beam over-heats the target
 - Too little beam produces much less isotopes
 - Cycling the beam on and off ages the target
- Closed-loop feedback has been used for more than 8 years for single beam line current stability and position stability
- Current stability existed, using an electrostatic deflector for only one beam line but decreased stability on other beam lines
- A proposal to stabilize the split ratio of two beam lines using a harmonic coil was advanced
- The suggestion uses a Bz magnetic field to alter the split ratio of the two extracted beams

BEAM CURRENT ADJUSTMENT BY HARMONIC COIL

- The cyclotron accelerates H- and uses stripping foil extraction to extract protons
- Trim and harmonic coils exist to alter the beam path of the H- as it spirals out
- The coils provide radial (B_r) and vertical (B_z) magnet field components, which move the beam vertically and radially (horizontally) respectively
- The ratio of the currents extracted is determined primarily by the relative position of the circulating/accelerating beam to the position of the two extraction foils
- By moving the beam horizontally using the B_z , current can quickly be re-positioned from one foil to the other
- The harmonic coil is a virtual device comprising six power supplies and related coil windings
- A separate process monitors two extracted currents and calculates the split ratio
- The feedback loop software adjusts the beam position to stabilize the split ratio

DEVICE IMPLEMENTATION


- There are thirteen sets of harmonic coils
- Each set comprises six pairs of coils located in a 6-fold symmetrical manner in the cyclotron tank
- They are used to adjust the local magnet field at a particular radius
- Harmonic coil 13 is the outermost set and was chosen for use in the split ratio stability program
- There are six parameters for this harmonic coil:
 - The 1st harmonic amplitude for B_r and B_z
 - The 1st harmonic phase for B_r and B_z
 - The 3rd harmonic amplitude for B_r and B_z
- Each parameter is implemented as a virtual device

PLANS FOR ENHANCEMENTS

- Install higher resolution DACs to improve control
- Improve software algorithms
- Use the pulser to stabilize the injected current


APPLICATION PROGRAM FEATURES/USER INTERFACE

- Application program reads the split ratio, compares it to the target value and adjusts the B_z (horizontal beam position) if necessary
- User interface has three parts:
 - Summary control and monitoring page for stability program
 - Detailed control and monitoring page for virtual devices
 - Control from the main console
- State changes and user changes to parameters are automatically recorded in the master log



OPERATIONAL EXPERIENCE

- Running for almost one year
- Regularly used in normal operation
- Increased stability achieved
- Less beam trips
- Less Operator intervention needed



SUMMARY

- Increased beam current stability has been achieved
- Split ratio stability software is now used in normal operation
- User interface and closed-loop application are well accepted by Operations
- Reliable operation over the last year
- Operation of the Cyclotron is easier because less Operator intervention is needed
- Further enhancements are anticipated