# Study on New Removal Thickness Distribution Improvement Methods for Niobium 9-cell Cavity Vertical Electropolishing

# with Ninja Cathode

Keisuke Nii<sup>O</sup>, Vijay Chouhan, Yoshiaki Ida, Takanori Yamaguchi (Marui Galvanizing Co., Ltd.)


Hitoshi Hayano, Shigeki Kato, Hideaki Monjushiro, Takayuki Saeki, Motoaki Sawabe (High Energy Accelerator Research Organization (KEK))



Marui Galvanizing Co., Ltd. has been developing niobium 9-cell cavity vertical electropolishing (VEP) technologies with Ninja cathode in collaboration with KEK. Conventional 9-cell cavity VEP had a serious problem, which was asymmetry of removal thickness distribution. Usually removal thickness of upper side became larger than lower side in case of both in-cell and inter-cell. So far, as one solution, we proposed "bubble diffusion prevention" method and proved it was effective for uniform removal. This time, as other new solution, we tried "cavity flip upside down" and "Ninja cathode masking" VEP methods. In this article we will report the purpose, intention and VEP experiment result of these methods.

### Introduction

In 9-cell cavity VEP, removal thickness non-uniformity of internal cell and inter-cell is a big problem.



This time, we developed other new removal thickness improvement methods.

- Cavity flip upside down
- Cathode masking We performed VEP tests using them and evaluate the results.




Ninja cathode



VEP condition

Removal thickness

Cavity flip upside down procedure





- Coupon surface roughness after VEP
- Average coupon current during VEP was made uniform by cavity flip upside down.
- ·The cavity removal thickness was made uniform as compared with the usual VEP
- ·Lower cavity coupon surface became rough. It seems due to setup asymmetry.





With masking Ninja Viewport inspection(TC\_TI)





In order to confirm the effect of masking, cathode for upper 5 cell were masked and compare with no masking parts and masking parts.

Although the amount of polishing was greatly reduced by masking, little polishing was done (<10um).

Rough surface was found in upper 5cell (masking parts)

## Next step improvement

Coupon surface after VEP

Cavity flip upside down VEP

- · Improvement of cathode rotation part sealing
- →Smooth rotation, leakage prevention, make cathode rotatable in reverse position
- ·Improvement of flip upside down system→Smooth and repeatable flip
- •Setup symmetry improvement→Use same shape inlet and outlet parts

## Masking VEP

Optimization of masking shape→Removal uniformity and surface optimization

# Summary

- To test the new removal thickness distribution. improvement methods, we performed and evaluated cavity flipe upside down VEP and cathode masking VEP.
- Removal thickness uniformity was improved on cavity flip upside down VEP. Masking was somewhat effective however surface became rough.
- ·We will further improve the equipment and optimize the condition, and improve the surface and achieve performance of ILC specification.