

Process #	Flow	Operation Details			
Catergori	Catergorize process				
1		Inspect a packaging box to see if there is any damage due to the folk lift and/or during transportation.			
2	10 POWER PACK UNIT SAETY 10 POWER PACK UNIT SEM 51512 Nation 900000000000 AC 10 POWER PACK UNIT SEM 10 POWER PACK UNIT SEM	Scan the serial number of the packaging box			
3		Remove bands			

4	*Operated by 2 or more operators.
5	Remove side walls *Operated by 2 or more operators.
6	Inspect side walls to see if there is any damage due to the contact with coolant ports, connectors and rear bracket.
7	Inspect the following items - the deformation of the layer - BOB tilted or come off - Plastic sheet shifted etc

8		*Operated by 2 or more operators.
9	CARB POWER PACK UNIT LI MM (NMC)-C.F/PPE, YYMM Vmin0 pack: 172.5V Vmin0 cell:2.5V Vmin0 cell:2.5V Vmin0 cell:2.5V Prine Planet Energy Dation Co.J. 05193204\$#-T00PPDDDY%0001 Mrg. by Prine Planet Energy Dation Co.J.	Scan each serial number of 2 batteries of the 1st layer
10		Inspect plastic sheets to see if there is any damage on them.
11		Inspect the top covers to see if there is any damage on them. Criteria - under documentation.





19		*Operated by 2 or more operators.
20		Remove bands
21	B Good to be used	Category labels are attached on the packaging box.