PLANT 2 Maintenance Procedure	Filler Lubrication and Valve Seal Inspection		
	Document No.: **MP-501**	Revision: **B**	Effective: **2020-02-17**
Department: Maintenance	Prepared by: K. Petrov	Approved by: J. Brandt	

1.0 PURPOSE

Keep the rotary fillers filling accurately by lubricating the carousel and catching worn valve seals.

2.0 SCOPE

FIL-1, FIL-2 and FIL-3. Covers the 14-day lubrication task and the 90-day valve seal inspection in the maintenance system.

3.0 RESPONSIBILITIES

Role	Responsibility
Maintenance Technician	Carries out the work.
Maintenance Planner	Schedules the work with production.
Shift Lead	Releases the line.

4.0 SAFETY AND MATERIALS

Personal protective equipment: Safety glasses; Nitrile gloves; Safety shoes

Materials: Food-grade grease (H1); Fill valve seal kit

Tools: Grease gun; Nozzle wrench; Seal pick; Inspection light

5.0 RELATED DOCUMENTS AND RECORDS

Documents: SP-402 Lockout/Tagout; WI-210 Filler Setup and Nozzle Check

Records: Maintenance work order

6.0 EVERY 14 DAYS: LUBRICATION AND NOZZLE INSPECTION

1. *Maintenance Technician:* Lock out the filler as described in SP-402.
2. *Maintenance Technician:* Grease the carousel bearing and the lift cams: 3 strokes at each point. Use only food-grade H1 grease.
3. *Maintenance Technician:* Inspect every nozzle tip for nicks and build-up. Clean or replace.
4. *Maintenance Technician:* Remove locks. Run the filler empty for 2 minutes and listen for noise.

7.0 EVERY 90 DAYS: VALVE SEAL INSPECTION

1. *Maintenance Technician:* Lock out. Remove two valves, chosen from different sides of the carousel.

2. *Maintenance Technician:* Inspect the seals for flat spots, cuts and swelling. If either valve shows wear, inspect all valves.
3. *Maintenance Technician:* Replace worn seals. If more than a third are worn, replace the full set.
4. *Maintenance Technician:* After any seal change, the operator repeats the nozzle check in WI-210 before the line is released.
5. *Maintenance Technician:* Write what was found, valve by valve, on the work order. Do not close it with 'OK' alone.

8.0 REVISION HISTORY

Rev	Date	Change
B	2020-02-17	Seal inspection sample set at two valves.
A	2019-05-20	First issue.