PLANT 2 Quality Procedure	Customer Complaints and Lot Trace		
	Document No.: **QP-316**	Revision: **B**	Effective: **2020-11-02**
Department: Quality	Prepared by: H. Costa	Approved by: J. Brandt	

1.0 PURPOSE

Answer every customer complaint and find all product from the same lot.

2.0 SCOPE

All complaints about product made at Plant 2.

3.0 RESPONSIBILITIES

Role	Responsibility
Quality Manager	Owns each complaint until it is closed.
QA Technician	Carries out the lot trace.
Shift Lead	Supplies the production and downtime records for the shift.

4.0 SAFETY AND MATERIALS

Personal protective equipment: None

Materials: None

Tools: None

5.0 RELATED DOCUMENTS AND RECORDS

Documents: QP-315 Nonconforming Product and Hold

Records: FRM-QA-20 Complaint Record

6.0 LOT CODES

1. *QA Technician:* Every bottle carries a lot code in the form P2-L3-261104-A: plant, line, date as year-month-day, shift.
2. *QA Technician:* The lot code identifies the line and shift. Use it to pull the production report, the fill weight chart, the label roll log and the downtime log for that shift.

7.0 HANDLING A COMPLAINT

1. *Quality Manager:* Open FRM-QA-20 Complaint Record within one working day.
2. *QA Technician:* Trace the lot. List the materials used: bottle, cap and label lots.
3. *QA Technician:* Place any remaining stock from the same lot on hold as described in QP-315.

4. *Shift Lead:* Give the QA Technician the shift's records and any notes within one working day.
5. *Quality Manager:* Reply to the customer within 5 working days with the cause and the action taken.

8.0 REVISION HISTORY

Rev	Date	Change
B	2020-11-02	Reply time set at 5 working days.
A	2019-05-20	First issue.