WAREHOUSE PROCEDURE	Receiving and Put-Away		WH-601 Rev C
PLANT 2	Dept: **Warehouse**	Effective: **2023-06-19**	By: L. Mbeki Appr: D. Whitfield

Purpose

Receive materials safely, check them against the order, and keep them in quarantine until Quality releases them.

Scope

All deliveries at dock doors 1 to 4.

Roles

Role	Responsibility
Receiving Clerk	Checks the delivery against the purchase order.
Forklift Driver	Unloads and puts away.
Warehouse Supervisor	Assigns dock doors and resolves shortages.
QA Technician	Releases packaging materials.

PPE

- High-visibility vest
- Safety shoes
- Cut-resistant gloves

Tools

- Pallet jack
- Wheel chocks
- Barcode scanner

Materials

- Bottles
- Caps
- Labels
- Shipper cases
- Raw chemicals

Procedure

Unloading

Step	Who	Action
1	Warehouse Supervisor	Assign a dock door. Inbound packaging normally uses doors 3 and 4.
2	Forklift Driver	Chock the trailer wheels and lock the dock leveler before entering.
3	Forklift Driver	Drive at walking pace on the dock and in the receiving lanes: no faster than 3 mph.
4	Receiving Clerk	Check the delivery against the purchase order: item, quantity, lot numbers, damage. Note the time of arrival against the promised time.

Quarantine and put-away

Step	Who	Action
5	Receiving Clerk	Enter the delivery on FRM-WH-01 Receiving Log and in the inventory system.
6	Receiving Clerk	Packaging materials go to the quarantine lane with a yellow QUARANTINE tag until the QA Technician releases them (see QP-308).
7	Forklift Driver	After release, put away to the location on the tag. Oldest lot in front.
8	Warehouse Supervisor	A delivery more than 2 hours late, or short, is reported to Purchasing and to the Production Planner the same shift.

Related documents

- QP-308 Incoming Inspection of Packaging Materials
- SP-405 Forklift and Pedestrian Safety

Records

- FRM-WH-01 Receiving Log

Revision history

Rev	Date	Change
C	2023-06-19	Late delivery reporting added.
B	2022-06-13	Work-instruction template.