## ECE 552 Final Project Demo2

## Group member: Tingbiao Li, Yifan Li

Cycle	Instruction Retired	Reason
1	nop	
2	nop	Instruction reset
3	nop	
4	lbi r0, 0	
5	lbi r5, 43	
6	lbi r6, 43	
7	lbi r7, 43	
8	ld r1, r0, 0	
9	nop	RAW hazard. The instruction in line 12 need register r1
10	nop	from line 8, so here insert "nop" for waiting the value of r1
11	nop	write back
12	st r5, r1, 0	
13	ld r1, r0, 2	
14	nop	RAW hazard. The instruction in line 17 need register r1
15	nop	from line 13, so here insert "nop" for waiting the value of
16	nop	r1 write back
17	st r6, r1, 1	
18	ld r1, r0, 4	
19	nop	RAW hazard. The instruction in line 22 need register r1
20	nop	from line 18, so here insert "nop" for waiting the value of
21	nop	r1 write back
22	st r7, r1, 1	
23	halt	