




## Main Keyboard PCB



## Controller PCB



## 2-Key Expansion PCB



Solder the 4 jumpers on the PCB bottom side only:  
 - Right PCB: solder on side marked "L"  
 - Left PCB: solder on side marked "R"

