Decimal	Hexadecimal	Index		Decimal	Hexadecimal
4096	1000	1	1	0	0
4100	1004	2	2	4	4
4104	1008	3	3	8	8
4108	100C	4	4	12	С
4112	1010	5	5	16	10
4116	1014	6	6	20	14
4120	1018	7	7	24	18
4124	101C	8	8	28	1C
4128	1020	9	9	32	20
4132	1024	10	Α	36	24
4136	1028	11	В	40	28
4140	102C	12	С	44	2C
4144	1030	13	D	48	30
4148	1034	14	E	52	34
4152	1038	15	F	56	38
4156	103C	16	10	60	3C
4160	1040	17	11	64	40
4164	1044	18	12	68	44
4168	1048	19	13	72	48
4172	104C	20	14	76	4C
4176	1050	21	15	80	50
4180	1054	22	16	84	54
4184	1058	23	17	88	58
4188	105C	24	18	92	5C
4192	1060	25	19	96	60
4196	1064	26	1A	100	64
4200	1068	27	1B	104	68
4204	106C	28	1C	108	6C
4208	1070	29	1D	112	70
4212	1074	30	1E	116	74
		31	1F	120	78
		32	20	124	7C