2114 SRAM TESTER

		1	PCINT17	USART TXD	PD1	TX		Vin					
			PCINT16	USART RXD	PD0	RX		GND					GND
						/RST		/RST					
GND				i		GND		5V		Ī			Vcc
/CS		<u> </u>	PCINT18	INTO	PD2	D2		A7				ADC7	
/WE	PWM	OC2B	PCINT19	INT1	PD3	D3	N	A6				ADC6	
A0		T0	PCINT20	USART XCK	PD4	D4	Α	A5	PC5	2-Wire SCL	PCINT13	ADC5	LED RED
A1	PWM	T1/OC0B	PCINT21		PD5	D5	N	A4	PC4	2-Wire SDA	PCINT12	ADC4	LED GREEN
A2	PWM	AIN0/OC0A	PCINT22	i	PD6	D6	0	А3	PC3		PCINT11	ADC3	D3
A3		AIN1/OC2B	PCINT23	<u> </u>	PD7	D7		A2	PC2		PCINT10	ADC2	D2
A4		ICP1	PCINT0	CLKO	PB0	D8		A1	PC1		PCINT9	ADC1	D1
A5	PWM	OC1A	PCINT1	 	PB1	D9		A0	PC0	<u> </u>	PCINT8	ADC0	D0
A6	PWM	OC1B	PCINT2	SPI/SS	PB2	D10		AREF		Ī			
A7	PWM	OC2A	PCINT3	SPI MOSI	PB3	D11		3V3		<u> </u>			
A8			PCINT4	SPI MISO	PB4	D12		D13	PB5	SPI SCK	PCINT5		A9
	<u>. </u>						USB						

18 Vcc A5 17 Α7 A8 15 Α9 14 D0 Α1 13 D1 A2 12 D2 /CS 11 D3 GND /WE