

## **Disassembly Run 6 – January 10<sup>th</sup>, 2025**

**Production Order:** \_\_\_\_\_



**Quality:** Total Loss (TL)

**Kinexon:** Totalschaden


**Delivery time:** \_\_\_\_\_


**Other Comments:**

Step	Tool	Task	Image	Comment
WS 1 – Step 1 (1): Remove body and spoiler → to warehouse: Body & Spoiler (BOSP)				
1.1		Loose splints (2x)		
1.2	<b>Remove BOSP</b>	Remove body (1x) Remove spoiler (1x)		
1.3	 <b>BOSP</b>	Connect BOSP Body (1x) & spoiler (1x)	 <b>BOSP</b>	
1.4	 <b>BOSP</b>	Body & Spoiler → Warehouse		

Step	Tool	Task	Image	Comment
WS 1 – Step 2 (2): Remove battery → to warehouse: Battery (BAT)				
2.1		Disconnect battery cable		
2.2		Loose splints (2x) Loose cable clip (1x)		
2.3	<b>Remove BAT</b>	Remove battery		

Step	Tool	Task	Image	Comment
2.4	 BAT	<b>Connect BAT</b> Battery		
2.5	 BAT	Battery → Warehouse		
2.6	 CREW	Keep initial tracker at <b>Chassis, Remaining systems, Engine, and Wheels</b>	 No connection needed!	
2.7	 CREW	Remaining parts (CREW) <b>→ Buffer B2 (Workstation 2)</b>		

Step	Tool	Task	Image	Comment
WS 2 – Step 3 (3): Remove rear tires → to warehouse: Rear Tires (RT)				
3.1		Loose cap nuts (2x)	 	
3.2	<b>Remove RT (2x)</b>	Remove rear tires (2x)		
3.3	 <b>RT (2x)</b>	<b>Connect RT</b> Rear tires (2x)	 <b>RT</b>	
3.4	 <b>RT (2x)</b>	Rear tires (2x) → Warehouse		

Step	Tool	Task	Image	Comment
WS 2 – Step 4 (4): Remove front tires → to warehouse: Front Tires (FT)				
4.1		Loose cap nuts (2x)		
4.2	<b>Remove FT (2x)</b>	Remove front tires (2x)		
4.3	 FT (2x)	<b>Connect FT</b> Front tires (2x)		
4.4	 FT (2x)	Front tires (2x) → Warehouse		
4.5	 CRE	Keep initial tracker at Chassis, remaining systems, and engine (CRE)	 No Connection needed!	
4.6	 CRE	Chassis, remaining systems, and engine (CRE) → Warehouse		

