



## <u>Problems with typical approach – Static Lay:</u>

- 1) Unrealistic compression in product
- 2) Produce long free-spans
- 3) Longer offshore time

