









i Important!

This replacement procedure can be used for: BMW X5 (E53) 3.0 d, BMW X5 (E53) 4.6 is, BMW X5 (E53) 3.0 i, BMW X5 (E53) 4.4 i, BMW X5 (E53) 4.8 is

The steps may slightly vary depending on the car design.

CLUB.AUTODOC.CO.UK 1-8







Replacement: pollen filter – BMW X5 E53. Tip from AUTODOC:

- Replace the cabin filter at least once every six months, in early spring and autumn seasons.
- Follow the terms, recommendations and requirements of the part operation provided by the manufacturer.
- If the air flow into the cabin has sharply reduced, replace the filter before a scheduled maintenance.
- All work should be done with the engine stopped.

REPLACEMENT: POLLEN FILTER – BMW X5 E53. RECOMMENDED SEQUENCE OF STEPS:

1

Open the bonnet.



- Use a fender protection cover to prevent damaging paintwork and plastic parts of the car.
- Unscrew the fasteners of the cabin filter housing cover.



CLUB.AUTODOC.CO.UK 2-7







Raise a little the cabin filter housing cover.



Remove the cabin filter.



Replacement: pollen filter – BMW X5 E53. Professionals recommend:

• Do not attempt to clean and reuse the filter - it will affect the quality of air cleaning inside the car.

Install the cabin filter to its mounting seat.



CLUB.AUTODOC.CO.UK 3-7







AUTODOC recommends:

- Follow the air flow direction arrow on the filter.
- Replacement: pollen filter BMW X5 E53. Be sure to position the filtering element correctly. Avoid misalignment.
- Take care to only use quality filters.



8

9



Screw in the fasteners of the cabin filter housing cover.



Remove the fender protection cover.

CLUB.AUTODOC.CO.UK 4–7







10

Close the hood.





VIEW MORE TUTORIALS


CLUB.AUTODOC.CO.UK 5-7







AUTODOC — TOP QUALITY AND AFFORDABLE CAR PARTS ONLINE



A GREAT SELECTION OF SPARE PARTS FOR YOUR CAR

BUY SPARE PARTS FOR BMW

POLLEN FILTER: A WIDE SELECTION

CLUB.AUTODOC.CO.UK 6-7