
DAC Test

0V-4.1V Sweep



0.03V comes out to 0.6% error

