

Inspection And Verification



1. Verify the customer concern.
2. Visually inspect for obvious signs of mechanical or electrical damage.

Visual Inspection Chart

Mechanical	Electrical
• Battery • Battery mounting	• Battery cables • Battery posts

3. If an obvious cause for an observed or reported concern is found, correct the cause (if possible) before proceeding to the next step.
4. If the fault is not visually evident, GO to Pinpoint Test A in the Pinpoint Test procedure.