


# Valve Tappet Inspection



## OHC engines

1. Inspect the valve tappet for damage, especially in the indicated areas. If any damage is evident, inspect the camshaft lobes and valves for damage. Replace components as necessary.



## Push rod engines

