



Warning
Do not attempt to diagnose or troubleshoot Supplemental Restraint System circuitry without consulting the Workshop Manual. Improper troubleshooting could cause the supplemental restraints to deploy inadvertently, causing injury.

OCCUPANT
CLASSIFICATION
SYSTEM
MODULE (OCSM)
151-39

BTS_SIG

BTS_VREF

C3159 VR210 BU-BN

LR142 YE-BU S381

S380

VR210 BU-BN C312

LR142 YE-BU

Super Cab

if equipped

C316

VR210 BU-BN C829

LR142 YE-BU

SAFETY BELT
TENSION
SENSOR (BTS),
PASSENGER
151-44

BTS_SIG

BTS_VREF

GND

2 C829

GD174
BK-WH

if equipped

3 C316

S321

GD174
BK-WH

G300
10-17

Regular Cab, Super Crew

C3238

BTS_SIG

BTS_VREF

GND

SAFETY BELT
TENSION
SENSOR (BTS),
PASSENGER
151-39

2 C3238

S351

GD901
BK

5 C312

GD174
BK-WH

G300
10-17

