

Furuno DRS4D-NXT

X-Band Radar
(Radome Unit)

Power Supply

12V DC

gain/PW
commands

4-bit
echo data

12V

Raspberry Pi
Controller

Software Loop

1. Read scan
(4-bit data)

2. Decide next
gain setting

3. Send
command

4. Log &
process data