





Equipment key

1 Computer and sensors



Shown heading $\psi = 90^\circ$ · bow faces north.

Positive r turns counterclockwise.