

Ezzoworks Pte Ltd

BIZLINK CENTRE Singapore

+65 96320750

david@ezzogenics.com

Company Registration No. 202224892K

### **ADDRESS**

MCST 2897 Changi Rise David Ng (MCST2897 Changi Rise Condo) 14 Simei Rise, Singapore 528806

Tel: 6785 5203 HP: 91995003

# **Quotation QE1122CHR1**

**DATE** 08/11/2022

#### **SALESMAN**

DC

ACTIVITY	QTY	RATE	AMOUNT
Sanding and Varnishing Location: Wood decking @ Changi Rise Condo	8,950	2.00	17,900.00

1. Sanding and varnishing of existing timber decking using Renner (From Italy) Aquaris Water-Based Outdoor Coating

or similar imported grade For the following area:

- a. Main entrance 620sqft
- b. Pathway and bridge area 930 sqft
- c. Side Gate 670 sqft
- d. Pool deck area 950sqft
- e. Small pond bridge 180sqft
- f. Blocks L1 Walkways with total 11 Blocks in total -

5600sqft

ACTIVITY QTY RATE AMOUNT

18,750.00

## **Repair** 1 18,750.00

- 2. Spot replacement for the following areas by way of replacing with Balau wood of similar size. To include replacement of damaged wood.
- a. Blk 2 (145mm W x 40mm T x up to 2178mm L) 2 pcs
- b. Blk 4 (145mm W x 40mm T x up to 2178mm L) 8 pcs
- c. Blk 6 (145mm W x 40mm T x up to 2178mm L) 3 pcs
- d. Blk 8 (145mm W x 40mm T x up to 2178mm L) 3 pcs
- e. Bridge in front of Blk 6 (145mm W x 40mm T x up to 2178mm L) 6 pcs
- f. Bridge between Blk 6 and Blk 8 (L 3m x 180mm W) 15 pcs
- g. Blk 10 (145mm W x 40mm T x up to 2178mm L) 1 pcs
- h. Blk 12 (145mm W x 40mm T x up to 2178mm L) 1 pcs
- I. Blk 14 Clubhouse area next to wading pool (145mm W
- x 40mm T x up to 2178mm L) 10 pcs
- j. Blk 16 (145mm W x 40mm T x up to 2178mm L) 2 pcs
- k. Blk 18 (145mm W x 40mm T x up to 2178mm L) 1 pcs
- I. Walkway and bridge next to Blk 18: 9 pcs
- m. Blk 20 (145mm W x 40mm T x up to 2178mm L) 2 pcs
- n Blk 22 (145mm W x 40mm T x up to 2178mm L) 5 pcs
- o. Blk 24 (145mm W x 40mm T x up to 2178mm L) 8 pcs
- p. Support beams to be replaced for the various location 10pcs with labour to replace \$2000
- Total from items 2a to 2o 67x pieces @ \$250 per piece (Supply and install) = \$16750

Repair 1 3,800.00 3,800.00

- 3. Sanding and varnish for existing tree clumps with replacement of missing Balau kerb
- a. Per set of tree clump with 3 pieces of decking wood @\$200 x 10 clumps = \$2000
- To install new Balau wood of missing or damaged wood kerb
- Total 15x pieces to replace x \$120 per pc \$1800

#### Terms & Conditions:

- (1) All quoted works are quoted as-is only. Non-quoted items shall be subjected to additional charges.
- (2) If changes are made to the work scope by shifting, amending, correcting or re-doing any work (be it completed or already started) due to change of plan by the customer and through no fault of the contractor, additional charges shall be incurred.
- (3) Job is confirmed with the invoice issued and deposit paid with quotation signed and stamped. Deposit paid is not refundable. Approved purchase order cannot be cancelled unless otherwise approved by the Contractor.
- (4) Payment terms: As stated in the quote. We reserve the right to stop work if any payment due is not paid.
- (5) Pay by cheque: "Ezzoworks Pte. Ltd" or
- OCBC Bank: 6018 7393 8001 or Paynow: 202224892K
- (8) The validity of quotation:14 days.
- (9) Please sign and stamp on this quotation.

Accepted By

Accepted Date