## Ezzogenics Pte. Ltd.

59 Ubi Avenue 1 #06-16 Bizlink Centre Singapore S408938 +65 69683098 admin@ezzogenics.com www.ezzogenics.com Company Registration No. 201208665Z

## Quotation QE0222MDL01



## **ADDRESS**

Alex @ 33 Mandalay Road 33 Mandalay Road, The Ansley 308214

DATE 03/02/2022 TOTAL SGD 8,150.00

## **PROJECT**

The Ansley 03-02

ACTIVITY	QTY	RATE	AMOUNT
Job description: Due to extensive damage to the parquet and marble flooring from prolonged soak with dirty sewage water, the following are adviced: a. Parquet - removal of damaged plywood and install with new plywood and parquet of similar quality. To also provide waterproofing coating prior to laying of plywood b. Marble - to provide marble sealer to prevent efflorescence affecting the marble polishing process. Efflorescence may occur due to the evaporation of moisture from the marble flooring (especially after prolonged soak in water)			
Hacking Wet Works  1. To remove and dispose existing dirty water damaged plywood base and to expose concrete base	1	1,200.00	1,200.00
Parquet Repair  2. Supply and install Maple Parquet (Maple from China) of size 18mm T x 95mm W x variable length 300-1200mm with the following work scope as part of installation a. Preparation of damaged flooring after removal of old plywood by provision of waterproofing membrane. (Water may have seeped affecting the flooring and subsequently raised the moisture content in the substrate concrete flooring - \$350 b. Installation of plywood underlay up to 9mm using WBP type plywood - \$550 c. Checking of levelling and moisture content of parquet and plywood d. Installation of Maple Parquet as per above specs - \$2250 e. To sand and varnish using Melamine Varnish - as part of item d - (option to change to Water-based varnish with top up \$100).	1	3,150.00	3,150.00
Skirting 3. Supply and install new skirting all around the apartment. Work scope includes: a. Removal of old skirting as these are already damaged by dirty water - \$600 b. Supply new materials and installation of new skirting. Material to be Nyatoh wood type skirting with oil-based paint to make good. Type of skirting to be S4S or Rounded top. \$850 c. Option of replacing Nyatoh wood with Maple skirting with Top Up - \$300	1	1,450.00	1,450.00

ACTIVITY		QTY	RATE	AMOUNT	
Marble Polishing  4. Supply materials and labour for Marble polishing at the Living Remarble laid flooring areas in unit. This includes diamond sanding, Stone Care Lab products. Diamond sanding, may require multiple different grit and polishing powder Includes repairing of minor grilling of missing grout.  Work scope:  a. Marble polishing using Diamond process  b. To provide Marble Sealer service to seal the surface of the macompleting the marble polishing process  Note:  1) Not possible to repair/fill deep cracks and sand/polish as new of the policy of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish as new of the polishing process stain and repair/fill deep cracks and sand/polish stain and repair/fill deep cracks and sand/polish stain and repair stain and re	polishing with passes with rout cracks and rble prior to condition.	1	1,150.00	1,150.00	
crack lines. We shall repair a reasonable small percentage of mir many places are affected, a new quotation will be given separate	or crack lines. If				
Partition Wall / False Ceiling  5. To remove existing damaged partition wall and make good. Incomignal placement provided the existing power outlet can be usefurther additional work can only be adviced upon removal of the cowall.  To also provide painting services and removal of damaged wally affected room.	luding re-wiring sed again. Any amaged partition	1	1,200.00	1,200.00	
Payment terms: 1. Deposit 50% upon confirmation 2. Balance 50% on completion					
Terms & Conditions:  (1) All queted works are queted as is only. Non queted items.					
(1) All quoted works are quoted as-is only. Non-quoted items shall be subjected to additional charges.	TOTAL		SGD 8,150.00		
(2) If changes are made to the work scope by shifting, amending, correcting or re-doing any work (be it completed or already started) due to change of plan by the customer and through no fault of the contractor, additional charges shall be incurred.				THANK YOU.	

(3) Job is confirmed with the invoice issued and deposit paid with quotation signed and stamped. Deposit paid is not refundable. Approved purchase order cannot be cancelled unless otherwise approved by the Contractor.

(4) Payment terms: As stated in the quote. We reserve the right to stop work if any payment due is not paid.

(5) Pay by cheque: "Ezzogenics Pte. Ltd" or

OCBC Bank: 555-846724001 or Paynow: 201208665Z

(8) The validity of quotation:14 days.

(9) Please sign and stamp on this quotation.

Accepted By **Accepted Date**