

GM3 - Fabrication Notes

GM11 - Board Outline + Cutouts

Notes: Copper up to cutout edge at customer risk

V-score lines on GM9



