Brass insert assembly machine pneumatic circuit(Right)

Parts List							
NO.	Parts name	specifition	Q'ty	Factory			
1	Plug valve	1/2"	1	SMC			
2	F.R.L	AC40A-04DG-A	1	SMC			
3	Brass moving Solenoid valve	TV2520-DC24V	1	DOYO			
4	Brass moving cylinder	MCDB-03-25-50M	1	Mindman			
5	Take the brass Solenoid valve	TV2510-DC24V	1	DOYO			
6	Take the brass cylinder	MCGB-03-16-30	1	Mindman			
9	Brass positioning Solenoid valve	TV2510-DC24V	1	DOYO			
10	Brass positioning cylinder	MCGJ-12-12-20	1	Mindman			
11	0-ring moving Solenoid valve	TV2520-DC24V	1	DOYO			
12	0-ring moving cylinder	MCJA-11-25-25M	1	Mindman			
13	0-ring throttle Solenoid valve	TV2510-DC24V	1	DOYO			
14	0-ring throttle cylinder	MCMJ-11-10-15-B	1	Mindman			
14	Pressing Solenoid valve	TV2510-DC24V		DOYO			
14	Pressing cylinder	FA-50-125R		DOYO			

Parts List							
NO.	Parts name	specifition	Q'ty	Factory			
17	Unload Solenoid valve	TV2520-DC24V	1	DOYO			
18	Unload cylinder	MCGD-03-12-50	1	Mindman			
19	0-ring blow Solenoid valve	TV2510-DC24V	1	DOYO			
20	0-ring blow tube	18-712-N16	1	泓陞			

