

## 4 Spindles screwing machine 文件集

0	2020/6/29	USER						
REV.	DATE	NAME	CHANGES					
stanley				risepower			REVISION	
								0
				CONTRACT:		User data 1		SCHEME
				20-603		User data 2		01

1-	Ż	r	
		_	

圖紙	功能	位置	校對	日期	創建人	說明	資料夾終點
01	=F1	+L1	0	2020/6/29	USER	首頁	
02	=F1	+L1	0	2020/6/29	USER	圖紙清單	
03	=F1	+L1	0	2020/6/29	USER	主迴路	
04	=F1	+L1	0	2020/6/29	USER	安全繼電器模組	
05	=F1	+L1	0	2020/7/13	USER	安全閘門電路	
06	=F1	+L4	0	2020/6/29	USER	鎖付起子迴路	
07	=F1	+L1	0	2020/6/29	USER	振筒+平送1	
08	=F1	+L1	0	2020/6/29	USER	控制電源迴路	
09	=F1	+L1	0	2020/6/29	USER	PLC OUTPUT0	
10	=F1	+L1	0	2020/7/13	USER	PLC OUTPUT1	
11	=F1	+L1	0	2020/7/13	USER	PLC OUTPUT2	
12	=F1	+L1	0	2020/8/4	USER	PLC OUTPUT3	
13	=F1	+L1	0	2020/6/29	USER	PLC INPUTO	
14	=F1	+L1	0	2020/7/13	USER	PLC INPUT1	
15	=F1	+L1	0	2020/7/13	USER	PLC INPUT2	
16	=F1	+L1	0	2020/7/13	USER	PLC INPUT3	

SOLIDWORKS Electrical

)						
Ź	risepower	<del>计</del> /护律:				REVISION
5	Посромсі	文件集				0
>			0 2020/6/29	USER		
5			REV. DATE	NAME	CHANGES	SCHEME
ĺ		LOCATION: 大京年中	User data 1		User data 2	02
ζ	CONTRACT: 20-603	LOCATION: +L1   主電氣室				02



























