POWER REQUIRMENTS FOR KIRK-RUDY 219B BASE

Kirk Rudy 219 Base 120Vac-20Amp 3 Prong Twist L5-20 (1)

Kirk Rudy Dryer 208-220 Volt Single Phase/30 Amp/ 3 Wire Twist NEMA L630 (2)

Feeder 110vac-15 Amp Plug (3)

The Ink Jet Base powers the Conveyor and Computer.

KR535 Tabber 120V 15Amp (4)

