










FLEX TRIM™ CARTER MILLWORK FLEXIBLE MOULDING

Bullnose Corner Radius Gauge





1. Print this PDF at “Actual” or “100%” scale.
2. Make your best radius estimate for the first attempt.
3. Cut along the line for the chosen radius.
4. Hold the page up to your bullnose corner.
5. If the page is flush with the wall, the radius is correct. If not, repeat with the next radius option.

